Bratcher, Mike, EMNRD

From: Gonzales, EL <ELgonzales@linnenergy.com>

Sent: Wednesday, May 11, 2016 9:11 AM

To: Bratcher, Mike, EMNRD

Cc: Michael Burton (mburton@diversifiedfsi.com)

Subject: RE: Linn - Turner B #114 - Work Plan & Reference to 2RP-935

Thanks, Mike: We will get this corrected (ASAP)----- E L

From: Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]

Sent: Wednesday, May 11, 2016 8:56 AM

To: Gonzales, EL

Cc: Michael Burton (mburton@diversifiedfsi.com); Laura Flores; djglass@blm.gov; Patterson, Heather, EMNRD

Subject: RE: Linn - Turner B #114 - Work Plan & Reference to 2RP-935

RE: Linn Operating * Turner B 114 * 30-015-29187 * 2RP-934 * DOR: 9/28/11

EL,

Your proposal for remediation of the above referenced release is approved. Federal sites will require like approval from BLM.

PLEASE NOTE: I have attached correspondence and a map, generated by Terry Gregston shortly after this release (2RP-934), and the release that should be attributed to <u>2RP-935</u>. Work that has recently been done at the Turner B 108 is <u>not</u> for the 2RP-935 release. At this time, OCD does <u>not</u> have a C-141 that corresponds with work that has been done at the Turner B 108 well site. As you can see from the TGregston map, releases identified as "A" and "B" are adjacent to each other. The map and correspondence show the north release (identified as "A"). This is <u>2RP-935</u>. The south release (identified as "B"), is this release, <u>2RP-934</u>. OCD suggests that analytical data be obtained from the actual 2RP-935 release site, a remediation proposal be submitted, and these two releases addressed at the same time. This would save mobilization costs, but working them together is up to Linn. At this time, the documents that reside under 2RP-935 in OCD database, will be removed and held until a C-141 is submitted and processed for the work that has been done on the Turner B 108 well site. It should be noted that the lat/long listed on both C-141s is accurate.

I understand this is confusing, and apparently was confusing when the releases occurred, in part to how, and what API number the releases were attributed to and entered in OCD database. If there are any questions, please contact me. Also, please submit a C-141 for work that has been done at the Turner B 108 so we can get that work entered properly.

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If you have any questions or concerns, and for notification, please contact me.

Mike Bratcher

NMOCD District 2 811 S. First Street Artesia, NM 88210 O: 575-748-1283 X108

C: 575-626-0857 F: 575-748-9720

From: Gonzales, EL [mailto:ELgonzales@linnenergy.com]

Sent: Wednesday, April 20, 2016 10:50 AM

To: Bratcher, Mike, EMNRD

Cc: Michael Burton (mburton@diversifiedfsi.com); Laura Flores

Subject: FW: Linn - Turner B #114 - Work Plan

Good morning, Mike: Here is a work plan for your review and approval ------ Thanks, EL

From: Laura Flores [mailto:lflores@diversifiedfsi.com]

Sent: Wednesday, April 20, 2016 10:37 AM

To: Gonzales, EL **Cc:** Michael Burton

Subject: Linn - Turner B #114 - Work Plan

Good morning, Mr. Gonzales.

Attached is the work plan for the Turner B #114, pending your review and approval.

Please let me know if you have any changes or questions.

Thank you,

Laura

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.