From: Blair, Yvonne B

To: <u>Patterson, Heather, EMNRD</u>

Cc: Conder, Haskell P; Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD

Subject: RE: BE-7-4 Loop C141.doc

**Date:** Thursday, December 01, 2016 1:46:15 PM

## Heather

Monday we will be hyrdrovacing lines and Tuesday at 8:30-9:00 am we will start the delineation of this line.

Yvonne Blair Compliance Coordinator DCP Midstream 575-361-2406

From: Patterson, Heather, EMNRD [mailto:Heather.Patterson@state.nm.us]

Sent: Thursday, December 01, 2016 1:13 PM

To: Blair, Yvonne B

Cc: Conder, Haskell P; Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD

Subject: RE: BE-7-4 Loop C141.doc

RE: DCP \* BE 7-4 Loop \* fAB1632651796 \* 2RP-4003

Yvonne.

Attached are the Conditions of Approval for this C-141 Remediation Permit. The OCD tracking number for this event is 2RP-4003.

Thank you,

Heather Patterson Environmental Specialist NMOCD District II Office (575)748-1283 ext.101 Cell (575)703-0228

**From:** Blair, Yvonne B [mailto:YBBlair@dcpmidstream.com]

Sent: Friday, November 18, 2016 7:56 AM

**To:** Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD

Cc: Conder, Haskell P

**Subject:** RE: BE-7-4 Loop C141.doc

Heather

## I do apologize my computer did not save correctly to PDF. I have corrected. It is BE-7-4 Loop

## Yvonne

From: Patterson, Heather, EMNRD [mailto:Heather.Patterson@state.nm.us]

**Sent:** Friday, November 18, 2016 7:49 AM **To:** Blair, Yvonne B; Bratcher, Mike, EMNRD

Cc: Conder, Haskell P

Subject: RE: BE-7-4 Loop C141.doc

Your email refers it as the BE-7-4 Loop, but the C-141 lists 10100 ext 2 as the facility name. Which name is correct?

Heather Patterson Environmental Specialist NMOCD District II Office (575)748-1283 ext.101 Cell (575)703-0228

**From:** Blair, Yvonne B [mailto:YBBlair@dcpmidstream.com]

Sent: Friday, November 18, 2016 7:39 AM

**To:** Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD

Cc: Conder, Haskell P

**Subject:** BE-7-4 Loop C141.doc

Correction on GPS location:

Heather/Mike

Good evening, attached is a the initial C141 for the Line leak BE-7-4 Loop for your review.

Yvonne Blair Compliance Coordinator DCP Midstream 575-361-2406