

## Bratcher, Mike, EMNRD

---

**From:** Christine Alderman <calderman@cimarex.com>  
**Sent:** Monday, October 9, 2017 3:10 PM  
**To:** Weaver, Crystal, EMNRD; Groves, Amber  
**Cc:** Bratcher, Mike, EMNRD  
**Subject:** RE: [External] RE: Darner 9 Sate 2 (API 30-015-37634)  
**Attachments:** IMG\_0716.jpg; IMG\_0718.jpg; IMG\_0722.jpg; IMG\_0721.jpg

All,

I was at the Darner 9 State #2 today and inspected the liner in approximately 5' intervals where the leak had occurred, and found no rips or tears. I have attached several pictures. Due to recent sporadic heavy rains the berm has continued to stay saturated, and has held the rain water. I am still having the foreman remove all the impacted gravel in the spill area when it is drier and I will more thoroughly inspect and report.

Please let me know if you have any questions or comments.

Respectfully,

Christine Alderman

Cimarex Energy Co.



ESH Supervisor – Permian Basin  
Midland TX  
Cell – 432.853.7059

---

**From:** Weaver, Crystal, EMNRD [mailto:Crystal.Weaver@state.nm.us]  
**Sent:** Monday, September 25, 2017 11:58 AM  
**To:** Christine Alderman <calderman@cimarex.com>; Groves, Amber <agroves@slo.state.nm.us>  
**Cc:** Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>  
**Subject:** [External] RE: Darner 9 Sate 2 (API 30-015-37634)

RE: Cimarex \* Darner 9 State #2 \* 30-015-37634 \* 2RP-4381

Christine,

Sorry for the delay on sending this one out. I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval. The OCD tracking number for this event is 2RP-4381. Please remit a site characterization plan or advise OCD of plan of action by no later than 10/08/17.

Thank you,

**Crystal Weaver**  
Environmental Specialist

OCD – Artesia District II  
811 S. 1<sup>st</sup> Street  
Artesia, NM 88210  
Office: 575-748-1283 ext. 101  
Cell: 575-840-5963  
Fax: 575-748-9720

-----Original Message-----

From: Weaver, Crystal, EMNRD  
Sent: Friday, September 8, 2017 2:15 PM  
To: Christine Alderman <[calderman@cimarex.com](mailto:calderman@cimarex.com)>; Groves, Amber <[agroves@slo.state.nm.us](mailto:agroves@slo.state.nm.us)>  
Cc: Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>  
Subject: FW: Darner 9 Sate 2 (API 30-015-37634)

Hello all,

I am forwarding this initial C-141 submission to Amber Groves of the State Land Office since my records show this site to be on state administered surface.

Thanks,

Crystal Weaver  
Environmental Specialist  
OCD – Artesia District II  
811 S. 1st Street  
Artesia, NM 88210  
Office: 575-748-1283 ext. 101  
Cell: 575-840-5963  
Fax: 575-748-9720

-----Original Message-----

From: Christine Alderman [mailto:[calderman@cimarex.com](mailto:calderman@cimarex.com)]  
Sent: Friday, September 8, 2017 9:53 AM  
To: Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; Weaver, Crystal, EMNRD <[Crystal.Weaver@state.nm.us](mailto:Crystal.Weaver@state.nm.us)>  
Subject: Darner 9 Sate 2 (API 30-015-37634)

We had a produced water release at the above named lease. The inlet connection on a fiberglass tank broke allowing all the water to release into a lined containment. 505 bbls of 507 bbls were recovered with vacuum trucks.

The impacted material will be removed and I will inspect the liner for breaches and report back to you my findings.

Thank you,

Christine Alderman

Cimarex Energy Co.

ESH Supervisor - Permian Basin  
Midland TX  
Cell - 432.853.7059

-----Original Message-----

From: MidlandScanner@cimarex.com [mailto:MidlandScanner@cimarex.com]  
Sent: Friday, September 08, 2017 10:47 AM  
To: Christine Alderman <calderman@cimarex.com>  
Subject: Message from "RNP0026732E6735"

This E-mail was sent from "RNP0026732E6735" (Aficio MP C5501).

Scan Date: 09.08.2017 10:46:50 (-0500)  
Queries to: MidlandScanner@cimarex.com