

## Venegas, Victoria, EMNRD

---

**From:** Venegas, Victoria, EMNRD  
**Sent:** Monday, April 22, 2019 1:47 PM  
**To:** 'DeAnn Grant'; Bratcher, Mike, EMNRD; caweaver@blm.gov  
**Cc:** Hamlet, Robert, EMNRD; McKinney, Deborah; jamos@blm.gov; Jennifer Knowlton; Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell  
**Subject:** RE: (C-141 Initial) Harvard Federal Tank Battery 03-30-2019

RE: (C-141 Initial) Harvard Federal Tank Battery 03-30-2019

All,  
The OCD tracking number for this release event is **2RP-5361**.  
Thank you,

Victoria Venegas  
EMNRD  
OCD-District II  
811 S First St. Artesia  
NM 88210  
[Victoria.Venegas@state.nm.us](mailto:Victoria.Venegas@state.nm.us)

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

---

**From:** DeAnn Grant <agrant@concho.com>  
**Sent:** Thursday, April 11, 2019 7:42 AM  
**To:** Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; caweaver@blm.gov  
**Cc:** Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>; McKinney, Deborah <dmckinne@blm.gov>; jamos@blm.gov; Jennifer Knowlton <jknowlton@concho.com>; Ike Tavarez <itavarez@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>; DeAnn Grant <agrant@concho.com>  
**Subject:** [EXT] (C-141 Initial) Harvard Federal Tank Battery 03-30-2019

Mr. Bratcher/Ms. Weaver,

Please find the attached C-141 for your consideration. Also, attached is the calculation sheet to determine the estimated release volume. The liquid lost estimate is based on the spill dimensions, estimated depth of fluid (wet soil depth) and type of formation. The spreadsheet will calculate the volume lost in the ground and does not include the recovered amount in the calculation. The calculated volume in the ground and the volume recovered were added together and reported on the C-141. If you have any questions or concerns please do not hesitate to contact me.

Thank you,

*DeAnn Grant*  
HSE Administrative Assistant  
[agrant@concho.com](mailto:agrant@concho.com)

COG Operating LLC  
600 W Illinois Avenue | Midland, TX 79701  
Direct: 432-253-4513 | Main: 432.683.7443

