## Hamlet, Robert, EMNRD

From: Shawna Chubbuck <shawna.chubbuck@soudermiller.com>

**Sent:** Thursday, November 7, 2019 10:38 AM

To: Hamlet, Robert, EMNRD

**Subject:** [EXT] Matador - Riser #4 (2RP-5113)

## Robert,

Per our conversation earlier today, I can confirm that the area around sample SW4, near the canal, was hand excavated, and then the sample was collected. The SMA staff's timesheet entry indicates on August 28, 2019 "on location guiding excavation of material against irrigation ditch by hand..." Prior dates to that entry are notes indicating coordination with the landowner for this work.

I hope this clarifies the amended report, we look forward to receiving closure for this release.

Thank you,

Shawna Chubbuck Senior Scientist

Personal Registrations: CO Listed Environmental Consultant (6328)
Corporate Registrations: AZ Engineering/Geology/Surveying Firm (14070), SD Surveying Firm (C-7436), TX Engineering Firm (8877), TX Geology Firm (50254), TX PST CAPM (CS-0000051), TX Surveying Firm (10162200), WY Engineering/Surveying Firm (S-1704)



## Souder, Miller & Associates

Engineering ♦ Environmental ♦ Surveying 112 W. Montezuma Ave.
Cortez, CO 81321-2758
www.soudermiller.com

(970) 565-4465 x1604 (office) (505) 488-8641 (mobile) (970) 565-4776 (fax)









Notice of Confidentiality and Privileged Status: This electronic mail message, including all attachments, is for the sole use of the intended recipient(s) and may contain confidential and/or privileged information or otherwise may be protected from disclosure. Any unauthorized review, use, disclosure, distribution or actions which rely on the contents of this information is prohibited. If you are not the intended recipient, please contact the sender and delete the message and any attachment(s) from your system.

Statement on Viruses and Harmful Software: While the message and attachment(s) have been scanned with anti-virus software, SMA does not guarantee that this message or any attachment(s) is free of computer viruses or other harmful software. SMA does not accept liability for any damages caused by any computer virus or other harmful software transmitted herewith.