Venegas, Victoria, EMNRD

From:	Venegas, Victoria, EMNRD
Sent:	Tuesday, June 4, 2019 11:55 AM
То:	'DeAnn Grant'; Hamlet, Robert, EMNRD; Bratcher, Mike, EMNRD; jamos@blm.gov
Cc:	dmckinne@blm.gov; Jennifer Knowlton; Ike Tavarez; Robert McNeill; Sheldon Hitchcock;
	Dakota Neel; Rebecca Haskell
Subject:	RE: (C-141 Initial) White Federal Com #001H (30-015-36185) 05-19-2019

[EXT] (C-141 Initial) White Federal Com #001H (30-015-36185) 05-19-2019

All, The OCD tracking number for this release event is <u>2RP-5470</u>. Thank you,

Victoria Venegas EMNRD OCD-District II 811 S First St. Artesia NM 88210 Victoria.Venegas@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

From: DeAnn Grant <agrant@concho.com>

Sent: Tuesday, June 4, 2019 11:11 AM

To: Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; jamos@blm.gov

Cc: Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>; dmckinne@blm.gov; Jennifer Knowlton <jknowlton@concho.com>; lke Tavarez <itavarez@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com> Subject: [EXT] RE: (C-141 Initial) White Federal Com #001H (30-015-36185) 05-19-2019

Mr. Hamlet,

The two releases were on separate days. It's coincidental that they each released 20 barrels from a flow line. The release on 5/17 overlapped the release on 5/13. Whereas, the release on 5/19 was in a different location. I apologize about the confusion and please let me know if you have any other questions.

Thank you,

DeAnn Grant

HSE Administrative Assistant agrant@concho.com COG Operating LLC 600 W Illinois Avenue | Midland, TX 79701 Direct: 432-253-4513 | Main: 432.683.7443



From: Hamlet, Robert, EMNRD [mailto:Robert.Hamlet@state.nm.us]
Sent: Tuesday, June 04, 2019 11:53 AM
To: DeAnn Grant <agrant@concho.com</p>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us</p>
; jamos@blm.gov
Cc: Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us</p>
; dmckinne@blm.gov; Jennifer Knowlton
<iknowlton@concho.com</p>
; Ike Tavarez <itavarez@concho.com</p>
; Robert McNeill <RMcNeill@concho.com</p>
; Sheldon
Hitchcock <SLHitchcock@concho.com</p>
; Dakota Neel <DNeel2@concho.com</p>
; Rebecca Haskell <RHaskell@concho.com</p>
Subject: [External] RE: (C-141 Initial) White Federal Com #001H (30-015-36185) 05-19-2019

**** External email. Use caution. **** DeAnn,

This looks identical to the C-141 for 5-17-19. Both wells have the exact same description, spill amounts, same name and API number, but different section numbers. Not sure what's going on with these two?

Thanks

From: DeAnn Grant <agrant@concho.com</p>
Sent: Tuesday, June 4, 2019 8:39 AM
To: Bratcher, Mike, EMNRD <<u>mike.bratcher@state.nm.us</u>>; jamos@blm.gov
Cc: Hamlet, Robert, EMNRD <<u>Robert.Hamlet@state.nm.us</u>>; Venegas, Victoria, EMNRD
<<u>Victoria.Venegas@state.nm.us</u>>; dmckinne@blm.gov; Jennifer Knowlton <<u>jknowlton@concho.com</u>>; lke Tavarez
<<u>itavarez@concho.com</u>>; Robert McNeill <<u>RMcNeill@concho.com</u>>; Sheldon Hitchcock <<u>SLHitchcock@concho.com</u>>;
Dakota Neel <<u>DNeel2@concho.com</u>>; Rebecca Haskell <<u>RHaskell@concho.com</u>>; DeAnn Grant <<u>agrant@concho.com</u>>;
Subject: [EXT] (C-141 Initial) White Federal Com #001H (30-015-36185) 05-19-2019

Mr. Bratcher/Mr. Amos,

Please find the attached C-141 for your consideration. Also, attached is the calculation sheet to determine the estimated release volume. The liquid lost estimate is based on the spill dimensions, estimated depth of fluid (wet soil depth) and type of formation. The spreadsheet will calculate the volume lost in the ground and does not include the recovered amount in the calculation. The calculated volume in the ground and the volume recovered were added together and reported on the C-141. If you have any questions or concerns please do not hesitate to contact me.

Thank you,

DeArw Grant HSE Administrative Assistant agrant@concho.com COG Operating LLC 600 W Illinois Avenue | Midland, TX 79701 Direct: 432-253-4513 | Main: 432.683.7443

