Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103		
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO	Revised June 10, 2003 WELL API NO.	
District II	OIL CONSERVATION DIVISION		30-005-60541		
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE		
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa 1 6, 14141 67303		6. State Oil &	Gas Lease No.	
87505					
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name	e or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Buckhorn AYU State Com		
PROPOSALS.)			8. Well Number		
1. Type of Well:		1			
Oil Well Gas Well X 2. Name of Operator	- DEULIVED		9. OGRID Number		
Yates Petroleum Corporation	MAR 2 5 2004		9. OGRID Nu	9. OGRID Number 025575	
3. Address of Operator	A 11 6 O		10. Pool name or Wildcat		
<u></u>	105 S. 4 th Street, Artesia, NM 88210 OCD-ARTESIA		Wildcat		
4. Well Location					
Unit Letter O : 990	feet from the	South line and	1980 feet from	n the East line	
Section18	Township 19S	Range20E	NMPMC	haves County	
	11. Elevation (Show wheth	er DR RKR RT GR et			
4724'GR					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INT		SUI	BSEQUENT F	REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WO	RK [ALTERING CASING [
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE D	RILLING OPNS.		
PULL OR ALTER CASING	MULTIPLE \[\bigcup \]	CASING TEST	AND CINA	ABANDONMENT	
	COMPLETION	CEMENT JOB		J	
OTHER:	Г	OTHER: Re-er	ntry procedures	X	
	ed operations. (Clearly sta	L			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion					
or recompletion.					
0/00 00/04 D	C1 1 1 11 050			~	
2/20-22/04 – Began re-entry procedures. Cleaned out well to 3735'. Drilled to 4-1/2" casing stub at 3810'. Circulated hole clean. 3/10/04 – TIH with 4-1/2" casing with slip over patch to 4-1/2" casing stub. Cemented with 500 sx "C" Neat.					
3/15/04 – Started drilling cement in 4-1/2" casing at 3600'. Drilled to 3850'. Circulated hole clean. Tested to 500#. Pulled above casing					
patch.					
3/16/04 – Started drilling cement at 3850'. Tagged tight spot at 3930'. Drilled and reamed out tight spot 3940'. Circulated hole clean.					
3/17/04 – Started drilling at 3940'. Drilled to 3965'. Circulated hole clean. TIH with 3 arm tool to 3913'. Pulled up to 3870'. Pulled back into gauged casing at 3870'.					
3/18/04 – Tagged up at 3880'. Tight spot to 3887'. Could work into casing. TOOH laying down tubing and drill collars. Nippled down					
BOP. Nippled up wellhead.					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
A · 1					
SIGNATURE:					
Type or print name Tina Huerta	· · · · · · · · · · · · · · · · · · ·	mail address: tinah@yp	cnm.com	Telephone No. 505-748-1471	
(This area Con Classical)					
	as fem	District 50	ganson	APR 0 6 2004	
APPPROVED BY Conditions of approval, if any:	TIT	LE		DATE	