

Step Rate Test


[illegible]

Toll Free
866-766-SWAT

Signal Wireline And Testing

Office
505-392-2048

Melrose Operating Co.
Artesia Unit #23
11/25/03



Parting pressure appears to be
1100 psi