Form 3160-5 (November 1983) (Formerly 9-331)

UNITED STATES DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIPLICATE *
Other Last Constant

Budget Bureau No. 1004-0135 Expires August 31, 1985

BUREAU OF LAND MANAGEMENT

fraudulent statements or representations as to any matter within its jurisdiction.

	13	301 W. Grand Ave	NU DIM 098122 LC 029420 A
SUNDRY NOTICES AND REPORTS ON WELESINM 8821			06. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do not use this form for prop	posals to drill or to deepen or plug back to	o a different reservoir.	
1.	CATION FOR PERMIT - " for such property	67897075	7. UNIT AGREEMENT NAME
OIL GAS WELL	OTHER	234567891017123233	Skelly Unit
2. NAME OF OPERATOR The Wiser Oil Company		/ JUL 2004 5	8. API WELL NO. 30-015-29092
3. ADDRESS OF OPERATOR		RECEIVED S	9. WELL NO.
P.O. Box 2568 Hobbs, N	lew Mexico 88241	a och ARTESIA	211
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 259' FSL & 1181' FWL			10. FIELD AND POOL, OR WILDCAT Grayburg Jackson 7-Rivers QN GB SA
259' FSL & 1181' FWL Unit M			11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
	<u> </u>		Sec. 15-T17S-R31E
14. PERMIT NO	15. ELEVATIONS (Show whether DF 3852' GR	F, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE Eddy County NM
16. Check	Appropriate Box to indicate Nat	ture of Notice, Report, or Oth	ner Data
NOTICE OF INTENTION TO:		BSEQUENT REPORT OF:	
TEST WATER SHUT OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT *
REPAIR WELL	CHANGE PLANS	(Other) Re-perf. & ac	
(Other)			esults of multiple completion on Well Recompletion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any			
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)			
12/02/03 MIRU Eunice Well Service. POH w/rods & pump. ND WH. RU BOP. POH w/2-7/8" tbg. LD BHA. RIH w/4-3/4" bit & 5-1/2" scraper on 2-7/8" tbg. to 3825'. POH w/tbg. LD tools. RU Computalog WL & perforate San Andres Grayburg f/3214'-16',50'-52',79'-81',3336'-40',85'-88',3410'-12',19'-23',31'-40',43'-51',55'-60',3522'-27',32',35'-38', & 46'-48' w/4 SPF. RD WL.			
12/03/03 RIH w/5-1/2" RBP & pkr. on 2-7/8" tbg. Set RBP @ 3800'. Pkr. @ 3500'. Test tbg. to 4000#. Held ok. Acidize Vac. 3500'-3800' w/2200 gals. 15% HCL acid w/anti-sludge & iron control w/2000# rock salt. Best block 1470#. Best break 1153#. ATP 2100# @ 4.5 bpm. MTP 3600# @ 4.8 bpm. Flush w/20 bbls. water. ISIP 1780#. 5 min. 1180#. 10 min. 850#. 15 min. 544#. 30 min. S.I. 210#. Moved RBP to 3500' & pkr. to 3150'. Acidize Grayburg San Andres w/3600 gals. 15% HCL acid w/anti-sludge & iron control w/2250# rock salt. Best block 300#. Best break 300#. ATP 2100# @ 4.4 bpm. MTP 2261# @. Flush w/40 bbls. water. ISIP 1850#. 5 min. 1417#. 10 min 1230#. 15 min. 1070#. 30 min. S.I. 700#. Left to flowline.			
12/04/03 Pick up RBP @ 3500'. POH w/2-7/8" tbg. LD tools. RIH w/2-7/8" tbg. Tbg. @ 3759'. SN @ 3727'. RD BOP. NU WH. RIH w/rods & 1-3/4" x 20' pump. Left well pumping to Battery "A". RDMO.			
18. I hereby certify that the foregoing is true	and correct.		
SIGNED // Jany Op Turney	TITLE Production To	ech II DA	ATE <u>March 30, 2004</u>
(This space for Federal or State office use)			ACCEPTED FOR RECORD
APPROVED BY	TITLE	DA	ATE
CONDITIONS OF APPROVAL, IF ANY:			JUL - 7 2004
	*See Instruction	on On Reverse Side	044)
ALEXIS C. SWOBODA Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States on the United S			