Office District I		New Mexico	Form C-
4 CAR 31 VI	Energy, Minerals	s and Natural Resources	Revised March 25,
1625 N. French Dr., Hobbs, NM 87240	_ -		WELL API NO.
District II	OIL CONSER	VATION DIVISION	30-015-3261-5
1301 W. Grand, Artesia, NM 87210 District III			5 Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		outh Pacheco	STATE FEE
District IV		e, NM 87505	State Oil & Gas Lease No.
2040 South Pacheco, Santa Fe, NM 87505	5		
SUNDRY NOT (DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPL PROPOSALS.) 1. Type of Well: Oil Well Gas Well	TICES AND REPORTS C	ON WELLS	6. Lease Name or Unit Agreement
(DO NOT USE THIS FORM FOR PROP	OSALS TO DRILL OR TO DEF	EPEN OR PLUG BACK-TO A	Name:
DIFFERENT RESERVOIR. USE "APPL	JCATION FOR PERMIT" (FOR	RM C-1912 FOR SUCHE OF	
PROPOSALS.)			Tucker Fee
Oil Well Gos Well	Other		
2. Name of Operator	U Oulei		7. Well No.
_	~ I I C /	18	7. WEII 140.
2 Address of Operator	II, L.L.C.	100 RECEIVED	1 Y
3. Address of Operator	0 3 4° 11 1 m	12 OOD WILLTRIN	8. Pool name or Wildcat
Nadel and Gussman Permia 3. Address of Operator 601 N Marienfeld, Suite 508 4. Well Location	s, Midiand, Texas 79	10/67 V	Esperanza Delaware (North) (97030)
4. Well Location		CB202 -01618	
TTta T	17003 0 0	00212200	2001
Unit LetterJ_:	:1600'feet from the	South line and 2	300' feet from the East line
Section 20	O Tammahim	21.6 Danes 27.E	NAME OF THE ORIGINAL OF THE OR
Section 28			NMPM Eddy Count
		whether DR, RKB, RT, GR, e	(c.)
11 61 1	2000		
		ndicate Nature of Notice,	
	NTENTION TO:	SUE	SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	N 🔲 📗 REMEDIAL WOF	RK 🔲 ALTERING CASIN
TEMPORARILY ABANDON	CHANGE PLANS		RILLING OPNS. PLUG AND
PULL OR ALTER CASING	3 MULTIPLE		ABANDONMENT
FOLL OR ALTER CASING L	COMPLETION	CASING TEST A	IND []
	COMIT ELTITOR	OLIVILIA 1 30B	
OTHER:		OTHER:	
12 Describe proposed or comple	eted operations (Clearly o	state all nertinent details and	give portinent dates, including actimated
12. Describe proposed or comple	eted operations. (Clearly s	state all pertinent details, and Multiple Completions: Attach	give pertinent dates, including estimated of
of starting any proposed work	eted operations. (Clearly and SEE RULE 1103. For	state all pertinent details, and Multiple Completions: Attac	give pertinent dates, including estimated on wellbore diagram of proposed complete
 Describe proposed or completed of starting any proposed work or recompilation. 	eted operations. (Clearly and k). SEE RULE 1103. For	state all pertinent details, and Multiple Completions: Attac	give pertinent dates, including estimated on wellbore diagram of proposed complete
of starting any proposed work	eted operations. (Clearly and k). SEE RULE 1103. For	state all pertinent details, and Multiple Completions: Attac	give pertinent dates, including estimated on wellbore diagram of proposed complete
of starting any proposed work or recompilation.	k). SEE RULE 1103. For	Multiple Completions: Attac	ch wellbore diagram of proposed completi
of starting any proposed work	k). SEE RULE 1103. For	Multiple Completions: Attac	ch wellbore diagram of proposed completi
of starting any proposed work or recompilation.	k). SEE RULE 1103. For	Multiple Completions: Attac	ch wellbore diagram of proposed completi
of starting any proposed work or recompilation.	k). SEE RULE 1103. For	Multiple Completions: Attac	ch wellbore diagram of proposed completi
of starting any proposed work or recompilation.	k). SEE RULE 1103. For	Multiple Completions: Attac	ch wellbore diagram of proposed completi
of starting any proposed work or recompilation.	k). SEE RULE 1103. For	Multiple Completions: Attac	ch wellbore diagram of proposed completi
of starting any proposed work or recompilation.	k). SEE RULE 1103. For	Multiple Completions: Attac	ch wellbore diagram of proposed completi
of starting any proposed work or recompilation.	k). SEE RULE 1103. For	Multiple Completions: Attac	ch wellbore diagram of proposed completi
of starting any proposed work or recompilation.	k). SEE RULE 1103. For	Multiple Completions: Attac	ch wellbore diagram of proposed completi
of starting any proposed work or recompilation.	k). SEE RULE 1103. For	Multiple Completions: Attac	ch wellbore diagram of proposed completi
of starting any proposed work or recompilation.	k). SEE RULE 1103. For	Multiple Completions: Attac	ch wellbore diagram of proposed completi
of starting any proposed work or recompilation.	k). SEE RULE 1103. For	Multiple Completions: Attac	ch wellbore diagram of proposed completi
of starting any proposed work or recompilation. Set 9-5\8" J-55 36 #/ft casing at 2.	k). SEE RULE 1103. For 200' instead of 2400'. All	Multiple Completions: Attac	ch wellbore diagram of proposed complete
of starting any proposed work or recompilation. Set 9-5\8" J-55 36 #/ft casing at 2.	k). SEE RULE 1103. For 200' instead of 2400'. All	Multiple Completions: Attac	ch wellbore diagram of proposed complete
of starting any proposed work or recompilation. Set 9-5\8" J-55 36 #/ft casing at 2. I hereby certify that the information	k). SEE RULE 1103. For 200' instead of 2400'. All on above is true and complete.	Multiple Completions: Attach	ch wellbore diagram of proposed complete
of starting any proposed work or recompilation. Set 9-5\8" J-55 36 #/ft casing at 2. I hereby certify that the information	k). SEE RULE 1103. For 200' instead of 2400'. All on above is true and complete.	Multiple Completions: Attach	the same.
of starting any proposed work or recompilation. Set 9-5\8" J-55 36 #/ft casing at 2. I hereby certify that the information	k). SEE RULE 1103. For 200' instead of 2400'. All	Multiple Completions: Attach	the wellbore diagram of proposed complete the same.
of starting any proposed work or recompilation. Set 9-5\8" J-55 36 #/ft casing at 2. I hereby certify that the information of the starting and the starting at 2.	on above is true and complete the complete true and complete the complete true and complete the complete true and comple	Multiple Completions: Attach	th wellbore diagram of proposed complete the same. The same of proposed complete the same of the same
of starting any proposed work or recompilation. Set 9-5\8" J-55 36 #/ft casing at 2. I hereby certify that the informatic SIGNATURE Kem/E. Type or print name Kem/E.	on above is true and complete the Cready	Multiple Completions: Attached Multiple Completions: Attached Attached Multiple Completions: Attached Multiple Completion Completi	the same.
of starting any proposed work or recompilation. Set 9-5\8" J-55 36 #/ft casing at 2. I hereby certify that the informatic SIGNATURE	on above is true and complete the Cready	Multiple Completions: Attach	tin the same. Idea and belief. Engineer DATE 02/05/03 Telephone No. 915-682-4429
of starting any proposed work or recompilation. Set 9-5\8" J-55 36 #/ft casing at 2. I hereby certify that the informatic SIGNATURE ** E. Type or print name ** Kem/E.	on above is true and complete the Cready	Multiple Completions: Attached Multiple Completions: Attached Attached Multiple Completions: Attached Multiple Completion Completi	th wellbore diagram of proposed complete the same. The same of proposed complete the same of the same