FORM 316049 20 21 22 23 23 VINITED STAT	Oil Cons.	FORM APPROVED BUDGET BUREAU NO. 1004-0135 EXPIRES MARCH 31, 1993
DEPARTMENT OF THE	EINTERION. Grand Avenue IAGEMENTESIA, NM 88210	5. LEASE DESIGNATION AND SERIAL NO. NMNM40256
SUNDRY NOTICES AND REF 10 NOTUSE THIS FORM FOR PROPOSALS TO DRILL, DEEPEN USE "APPLICATION FOR PERMIT"- FOR	, OR PLUG BACK TO A DIFFERENT RESERVOIR.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUBMIT IN TRIPLICATE 1. TYPE OF WELL		7. IF UNIT OR CA, AGREEMENT DESIGNATION
X OIL GAS OTHER		8. WELL NAME AND NO.
2. NAME OF OPERATOR TOM BROWN, INC.		Stott (H.W.) Fed 02
3. ADDRESS AND TELEPHONE NO.		9. API NO.
P. O. BOX 2608, MIDLAND, TX 79702 915-682-9715		30-015-25112
4. LOCATION OF WELL (Footage, Sec., T., R., M., or Survey Description) 2310' FWL, 860' FSL		10. FIELD AND POOL, OR EXPLORATORY AREA Fenton
SESW; Sec. 1; T21S, R27E UT . A		11. COUNTY OR PARISH, STATE
		Eddy, NM
CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION		OF ACTION
NOTICE OF INTENT	ABANDONMENT A RECOMPLETION	CHANGE OF PLANS NEW CONSTRUCTION
SUBSEQUENT REPORT	X PLUGGING BACK	NON-ROUTINE FRACTURING
	CASING REPAIR	WATER SHUT-OFF
FINAL ABANDONMENT NOTICE	ALTERING CASING	CONVERSION TO INJECTION
	OTHER	DISPOSE WAILER (Note Report results of multiple completion on Well
DESCRIBE PROPOSED OR COMPLETED OPERATIONS	(Clearly state all pertinent details, and give pertinent details	Completion or Recompletion Report and Log form)
DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estated date of starting any proposed work if well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*		
Recompletion Procedure: I,) DRILL OUT CIBP @ 2700'.		
MIRU Pluggers 2) SET CIBP @ 5500' and CAP W/35' CEMENT. NDWH NUROP pull tubing 3) SET 100' PLYG 4000-4100'. TAG		
TID TITLITODO I, pair tabing		
Set steel working pit 4) SET CIBP @ 2700' and CAP W/35' CEMENT, Pull stretch on 5 1/2" csg. If free to 2547 cut @ 2547, LD csg		
If free point is above 2550' cup @ free point and I D csg		
Spot cmt plug 2600-2500 and 1100-1050 NEED 100' PLUG @ CASING STUB.		
Perf Yates behind 8 5/8" csg from 700-720 w/ 1 jspf, 120 degree phasing premium charge (20 holes)		
PU tension pkr and TiH to 720 and spot 3 bbls 15% NEFE HCL		
Pull Pkr to 660 reverse 3 bbl into tbg and set pkr		
Acidize with remainder of 1000 gal 15% NEFE HCL + 30 ball sealers Swab to recover load and evaluate production		
Should production prove commercial, install artificial lift equipment and turn well to production		
If production is not commercial, set cmt plug 650-600, and 10 sx @ surf		
Install dry hole marker and remediate local		
NOTIFY BLM OFFICE AT LEAST	- 24 HOURS BEFORE COMM	LENCING PLUGGING OF
THEREBY CERTIFY THAT THE FOREGOING IS TRUE AND CORRECT. LOWER PORTION OF HOLE, 505-234-		
SIGNED JULI SURNEY	TITLE Vol Reptg Sup	DATE_03/05/03
(THIS SPACE FOR FEDERAL OR STATE OFFICE USE)		- 0 2003
(THIS SPACE FOR FEDERAL OR STATE OFFICE USE) APPROVED BY (ORIG. SGD.) ALEXIS C. SWOSODA TITLE PETROLEUM ENGINEER DATE 1 9 2003 CONDITIONS OF APPROVAL, IF ANY:		
——————————————————————————————————————		
Title 18 U.S.C. Section 1001, makes it a crim United States any false, fictitious or fra	e for any person knowingly and willfully to make to a audulent statements or representations as to any ma	any department or agency of the tter within its jurisdiction.
	F INSTRUCTIONS ON PEVEDSE SIDE	