Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

Lease Serial No. LC 069465

If Indian, Allottee or Tribe Name

FORM APPROVED

OMB No. 1004-0135 Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side				7. If Unit or CA/Agreement, Name and/or No.	
2. Name of Operator Saga Petroleum LLC	and the second s	/2	<i>A</i>	API Well	
3a. Address 415 W Wall, Suite 1900, I	Midland, TX 79701	3b. Phone No. (Welude (915)684-4293	Orefrode ?		Pool, or Exploratory Area
1980' FSL & 1650' FWL Sec. 3 (K) T16S-R30E (original staking plat show		nis oversized section	1500	AY/ County o Eddy Cou NM	nty
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NATU	RE OF NO TICE, R	EPORT, OR	OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
☐ Notice of Intent	☐ Acidize ☐ Alter Casing	☐ Deepen ☐ Fracture Treat	☐ Production (Start		☐ Water Shut-Off ☑ Well Integrity
X Subsequent Report	Casing Repair	New Construction	☐ Recomplete		Other
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	☐ Plug and Abandon☐ Plug Back	X Temporarily Abas☐ Water Disposal	ndon	
If the proposal is to deepen direc	d Operation (clearly state all pertinent ctionally or recomplete horizontally, e work will be performed or provide	give subsurface locations m	neasured and true vertical	depths of all pe	rtinent markers and zones.

Reference is made to Notice of Written Order - Carlsbad Field Office - James Amos No. 02JA126

95 jts (9792.61') 2-3/8" cmt lined tbg, 2-3/8" x 7" AD-1 pkr

2-20-03 NDWH, NUBOP, release pkr & TOOH, bullplug tbg, RIH, test every row of tbg to 2000 psi-all test good. POOH w/tbg, PU & RIH w/pkr, set, test csg-do not get good test, prep to strip off BOP & retest Release pkr, reset, packoff WH, load & test csg to 540 psi-30 mins-good MIT, chart approved by Van Barton

following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has

OCD by phone 2-21-03 - witness Phil Hawkins.

determined that the site is ready for final inspection.)

Please make note of Van Barton's letter dated April 10, 2003 confirming phone conversations w/Saga stating that the original chart was mailed from Saga's Hobbs office to the Midland office for submittal w/sundry notice of press test/mechanical integrity and was "lost in mail". Saga subsequently submitted a copy of the chart and was granted TA status by Artesia OCD.

Saga respectfully requests BLM approval of TA status based on OCD witness of test as chart copy previously submitted on 3-3-03 is not legible. I hereby certify that the foregoing is true and correct Name (Printed/Typed) **Production Analyst** Bonnie Husband

04/10/2003

FOR FEDERAL OR STATE OFFICE USE

Approved by lorig sed.) Joe G. Law

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.