Submit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		Form C-103 March 4, 2004
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-005-61049
1301 W. Grand Ave., Artesia, NM 88210			5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410			STATE X FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505		6. State Oil & Gas Lease No. LG-567
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name Grynberg LZ State
PROPOSALS.)		CEIVED	8. Well Number
1. Type of Well: Oil Well Gas Well X	0.4	6 2 7 7004	2
2. Name of Operator	•••		9. OGRID Number
Yates Petroleum Corporation 3. Address of Operator	OCD-ARTESIA		10. Pool name or Wildcat
105 South Fourth Street, Artesia, NM 88210			Pecos Slope Abo
4. Well Location			
Unit Letter G: 19	80 feet from the North	line and1	980 feet from the East line
Section 36 Township 5S Range 24E NMPM Chaves County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3864'GR			
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)			
Pit Location: ULSectTwpRngPit typeDepth to GroundwaterDistance from nearest fresh water well			
Distance from nearest surface water Below-grade Tank Location ULSectTwpRng;			
feet from theline and	feet from theline		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON X CHANGE PLANS MULTIPLE COMPLETION	REMEDIAL WOR COMMENCE DRI CASING TEST AT CEMENT JOB	LLING OPNS. PLUG AND ABANDONMENT
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
cement behind the casing to cover the cement behind the casing to the surface 4. Remove the wellhead and install a NOTE: Yates Petroleum Corporation	starting plugging work. d. x cement on top. Circulate hole wit 50 sx cement behind the casing to base of the 10-3/4" casing. Shoot e. Spot 5 sx cement at the surface dry hole marker, clean up location. will use steel pits and no earth pits	ith 10.0 ppg mud v cover the Glorieta 4 holes at 100' the to fill up the casing	Shoot 4 holes at 1000' and squeeze 50 sx n screw in a casing swage and squeeze 50 sx g if necessary.
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit or an (attached) alternative OCD-approved plan.			
SIGNATURE:			
Type or print name Tina Huerta	E-mail address	s: tinah@ypcnm	.com Telephone No. 505-748-1471_
(This space for State usa)	·		
APPPROVED BY Mi Hour Conditions of approval, if any:	Kens TITLE 4	ill Angs	DATE 9/1/04

Field: Pecos Slope Abo WELL NAME: Grynberg LZ State #2 Unit G Sec 36, 5S-24E 1980' FNL & 1980' FEL LOCATION: Chaves County GL: 3684' ZERO: **KB**: 3872' **CASING PROGRAM** 11/21/81 **COMPLETION DATE: 12/14/81** SPUD DATE: 10 3/4" 40.5# 950' 30-005-61049 COMMENTS: 4 1/2" 9.5# K55 4258' 14 3/4" hole Shoot 4 holes @ 978' & Sqz 50 Before 10 3/4" @ 950' w/450 sx cmtCirc) **TOPS** 542' San Andres Glorieta 1546' Fullerton 2956' Abo 3604 7 7/8" hole Toc@ 3090' by Cbl Abo Perfs: 3668-3916' w/16 .40" holes shot on 12-11-81 Acidize: 17000 g 10% Frac: Via tbg & Csng w/160000# 20/40 Sd on 12-15-81 126 jts 2 3/8" tbg set on 12/12/81 @ 3906' SN @ 3906' PBTD @ 4219' 4 1/2" @ 4258' w/350 sx cmt

TD 4250'

Field: Pecos Slope Abo WELL NAME: Grynberg LZ State #2 LOCATION: Unit G Sec 36, 5S-24E 1980' FNL & 1980' FEL Chaves County **GL**: 3684' ZERO: **KB**: 3872' **CASING PROGRAM SPUD DATE**: 11/21/81 **COMPLETION DATE**: 12/14/81 10 3/4" 40.5# 950' **COMMENTS**: 30-005-61049 4 1/2" 9.5# K55 4258' 50 SACKS OF squeeze heles@ 100' 10,0 Affer Shoot 4 holes @ 978' & Sqz 50 10 3/4" @ 950' w/450 sx cmtCirc) **TOPS** Squeeze holes @ 1.000' San Andres 542' 10.0 Glorieta 1546' **Fullerton** 2956 Abo 3604' 50 SACKS OF 77/8" hole 554ceze holes @ 1.6001 Toc@ 3090' by Cbl Perf's: 3668-3916' w/16 .40" holes shot on 12-11-81 Acidize: 17000 g 10% Frac: Via tbg & Csng w/160000# 20/40 Sd on 12-15-81 PBTD @ 4219' 4 1/2" @ 4258' w/350 sx cmt TD 4250