

N.M. Oil Cons. Div.-Dist. 2  
UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
301 W. Grand Avenue  
Alamogordo, NM 88210

Budget Bureau No. 1004-0135  
Expires August 31, 1985

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals.)		5. LEASE DESIGNATION AND SERIAL NO. NM-06407-B	
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> Injection		6. API Well No. 30-015-03858	
2. NAME OF OPERATOR Forest Oil Corporation		7. UNIT AGREEMENT NAME West Henshaw Premier Unit Tract	
3. ADDRESS OF OPERATOR P.O. Box 2568 Hobbs, New Mexico 88241		8. FARM OR LEASE NAME West Henshaw Premier Ut Tr 9	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface  3660' FNL & 330' FEL Unit I		9. WELL NO. 2	
10. FIELD AND POOL, OR WILDCAT West Henshaw Grayburg		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 4-T16S-R30E	
14. PERMIT NO	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3853' GL 3860' KB	12. COUNTY OR PARISH Eddy County	13. STATE N.M.
16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
(Other) Plug & Abandon			
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)			
Forest Oil requests approval to plug and abandon Grayburg/Premier injector by the procedure listed below. Perforation: Premier - 2797'-2806' & 2810'-2822'			
1. MIRU unit. ND WH. NU BOP. Release pkr. POH w/2-3/8" tbg. & pkr. 2. RIH w/4-3/4" bit and 2-7/8", 6.5# tbg. RIH to +/-2790'. POH w/bit. 3. RIH with 5-1/2" RBP and pkr. Set RBP at +/-2750'. Test casing to locate any possible casing leaks. Release pkr. and plug. POH with same. 4. RU WL. RIH and set CIBP at 2,750'. Dump 25' cement on plug. Perforate with 4 holes at 2,200'. RD WL. 5. RIH w/cement retainer and set at 2100'. RU cementing co. Sting into retainer and pump 75 sks. cement. Release from retainer and POH. 6. RU WL. Perforate at 480' with 4 holes. RD WL. 7. RIH w/pkr. and set at +/-300'. Pump 75 sks. cement. Leave no less than 100' cement in the the casing. Let cement set, release pkr. and tag top of cement. POH with pkr. 8. Set 60' of cement plug f/63' to 3'. RD cmt. company. RDMO. 9. Set dry hole marker.			
APPROVAL SUBJECT TO GENERAL REQUIREMENTS AND SPECIAL STIPULATIONS ATTACHED		<b>APPROVED</b> SEP 29 2004 LES BABYAK PETROLEUM ENGINEER	
18. I hereby certify that the foregoing is true and correct.			
SIGNED <u>Mary Jo Turner</u>		TITLE <u>Production Tech II</u>	
(This space for Federal or State office use)			
APPROVED BY _____		TITLE _____	
CONDITIONS OF APPROVAL, IF ANY:		DATE _____	

\*See Instruction On Reverse Side

Accepted for record - NMOCD

OPERATOR : FOREST OIL CORP

WELL : WEST HENSHAW PREMIER TR 9#2 LEASE No. : NM-06407B

LOCATION : 3660' FNL & 330' FEL - SEC 4 - T16S - R30E - EDDY COUNTY

