State of New Mexico Form C-103 Energy, Minerals and Namual Resources Department Revised 1-1-69 to Appropriate District Office OIL CONSERVATION DIVISION WELL APINO P.O. Box 1940, Hobby, NOM EEZ40 P.O. Box 2088 30-015-01605 Santa Fe, New Mexico 87504-2088 DISTRICTI S. Indicate Type of Laure P.O. Drewer DO, Artoria, NW EE210 STATE FEE L DISTRICT 6 State OI & Got Love No. 1000 Rio Bristor Rd., Astoc, NM 87410 B-11538 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Leaf Name or Unit Agrooment Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well: RECEIVED Red Lake Sand Unit Agr [X] war [Others 2. Name of Operator L Well Na MAR 3 1 7004 11 Mack Energy Corporation 9. Pool sume or Wildeau OCD-ARTESIA 1 Address of Operator Red Lake; Queen-Grayburg-SA P.O. Box 960, Artesia, NM 88211-0960 4 Well Location ._990 Line and 1650 Food From The ___ Unit Leace _ Feet From The North Linc 29 Eddy ~ 17S MMPM County 28E Socios Township 10. Elevacion (Show whether DF. RKB, RT. GR. dc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11 SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ALTERING CASING PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDONKENT X TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.

12. Describe Proposed or Com	placed Operations (Clearly state all per	tinent desails, and give portinent dates,	including estimated date of st	sarting any propond
worth SEE RULE 1103.	•			

OTHER:

CASING TEST AND CEMENT JOB

|--|

PULL OR ALTER CASING

OTHER:

	rag prug @ Z.		
3-09-04	RDMO. Install dry hole marker	& clean location.	
		-	
I berry ordity are a	a information above in true and complete to the best of my know	rinige and belief.	
SKIKATURE	for my	mu Agent	DATE3-23-04
THEOKIRATION	Roger Massey		тельно (432) 530-0907
(This open for State (~		
		_	OCT 2 1 2004
ATTROVED BY	- Held	— mu — A A A A	- DATE
~~~~~	~"	July Des V	
	<del></del>	8	

³⁻⁰⁸⁻⁰⁴ Tag plug @ 1670'

³⁻⁰⁸⁻⁰⁴ Circ. hole w/ mud.

³⁻⁰⁸⁻⁰⁴ Spot 35 sx cmt. @ 593', tag plug @ 470'.

³⁻⁰⁸⁻⁰⁴ Spot 25 sx cmt, from 60' to surface.

³⁻⁰⁹⁻⁰⁴ Tag plug @ 2'.



## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

## BILL RICHARDSON Governor

Joanna Prukop
Cabinet Secretary

PA OK TO Release

10/20/04

RECEIVED

OCT 1 5 2004

OCD-ARTER

Lori Wrotenbery
Director
Oil Conservation Division

Mack Energy Corp.
P. O. Box 960

5 April 2004

Artesia, New Mexico 88221-0960

Shend Shend

Form C-103 Report of Plugging for your Red Lake Sand Unit # 11 C-29-17-28 API 30-015-01605 Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

D	1.	All pits have been filled and leveled.
صم	٠.	Tan probation occasi sistem and to voice.

2. Rat hole and cellar have been filled and leveled.

3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)

4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.

5. The dead men and tie downs have been cut and removed.

6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.

7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Field Rep. II