RECEIVED

Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR

JAN 1 9 2005

FORM APPROVED OMB No. 1004-0135

#1

	DEFINITION OF THE	BINTERIOR	SA S	_	Expires January 31, 2004
BUREAU OF LAND MANAGEMENT					Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS					MNM12110
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					n, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side					or CA/Agreement, Name and/or N
1. Type of Well	N	MNM110992			
Oil Well 🖾 Gas Well 🚨 Other					ame and No.
2. Name of Operator					PEDORRO FEDERAL CO
MARBOB ENERGY CORPORATION					ell No.
3a. Address 3b. Phone No. (include area code)					15-31374
PO BOX 227, ARTESIA, NM 88211-0227 (505) 748-3303 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					d Pool, or Exploratory Arca
4. Location of Well (Foolage, Sec.		TREE DRAW; STRAW			
				11. County	or Parish, State
660 FNL 1650 FEL, SEC. 7-T17S-R28E, UNIT B					CO., NM
12. CHECK AP	PROPRIATE BOX(ES)	TO INDICATE N	ATURE OF NOTICE	, REPORT, OR	ROTHER DATA
TYPE OF SUBMISSION					
	Acidize	Deepen	Production (S	Start/Resume)	☐ Water Shut-Off
Notice of Intent	Alter Casing	☐ Fracture Treat	Reclamation		☐ Well Integrity
Subsequent Report	Casing Repair	New Construc	ction 🔲 Recomplete		Other
	Change Plans	Plug and Abar	ndon 🚨 Temporarily	emporarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	☐ Water Dispos	sal	
Attach the Bond under which the following completion of the invo	ctionally or recomplete horizon be work will be performed or policed operations. If the operational Abandonment Notices shall	tally, give subsurface rovide the Bond No. of on results in a multiple	locations and measured and on file with BLM/BIA. Re le completion or recompleti	I true vertical depti quired subsequent on in a new interv	ork and approximate duration then his of all pertinent markers and zo reports shall be filed within 30 dal, a Form 3160-4 shall be filed open completed, and the operator

MARBOB ENERGY CORPORATION PROPOSES TO PLUG & ABANDON AS FOLLOWS:

NOTIFY BLM 24 HRS BEFORE STARTING PLUGGING.

- POOH W/ TBG. SET CIBP @ 9080' (PERFS ARE @ 9118'-9144') W/ 35' CMT ON TOP.
- RIH & CIRC WELL W/ MUD.
- CUT & PULL 4 1/2" CSG @ 8400'.
- RIH. SPOT 100' STUB PLUG 50' IN & OUT. WOC. TAG.
- CUT & PULL 7" CSG @ 7400'.
- RIH. SPOT 100' STUB PLUG 50' IN & OUT. WOC. TAG. 6.
- POOH TO 3200'. SPOT 100' PLUG. 7.
- POOH TO 1560'. SPOT 100' PLUG (8 5/8" SHOE @ 1510'). WOC. TAG. 8.
- POOH TO 475', SPOT 100' PLUG (13 3/8" SHOE @ 425'), WOC. TAG.
- 10. SPOT 60' PLUG @ SURFACE.

	 	JLC M	ARACA					
4. I hereby certify that the foregoing is true and correct								
Name (Rrinted/Typed)		1						
DIANA J. CANNON		Title	PRODUCTION ANALYST	1				
Signature	Carra	Date	JANUARY 17, 2005	·				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Annealed by			Tid.	Date				

treemed for record . NMOCE Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.