Submit I Copy To Appropriate District State	of New Mexico	Form ( 102
Office	als and Natural Resources	Form C-103 October 13, 2009
1625 N French Dr , Hobbs, NM 88240		WELL API NO.
1301 W. Gland Ave, Altesia, WW 66210	RVATION DIVISION	30-015-23480     5. Indicate Type of Lease
1000 Pro Brazos Pd Aztec NM 87410	uth St. Francis Dr.	STATE 🗌 FEE 🖂
District IV Santa 1220 S. St Francis Dr, Santa Fe, NM	Fe, NM 87505	6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS	ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		Gissler AV
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS )		8. Well Number
1. Type of Well: Oil Well   Gas Well   Other		22     9. OGRID Number
2. Name of Operator Yates Petroleum Corporation		025575
3. Address of Operator		10. Pool name or Wildcat
		Eagle Creek San Andres
4. Well Location Unit Letter G : 2310 feet from the	North line and	2310 feet from the East line
Section 23 Township	17S Range 25E	NMPM Eddy County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
	3496' GR	
12 Check Appropriate Box t	o Indicate Nature of Notice	e Report or Other Data
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK DUID PLUG AND ABANDON REMEDIAL WORK DUID ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A		
PULL OR ALTER CASING  MULTIPLE COMPL CASING/CEMENT JOB		
OTHER: OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
1. MIRU WSC. Rig up any safety equipment as no	Acessany	
<ol> <li>MIRO WSC. Rig up any safety equipment as necessary.</li> <li>Set a CIBP at 1252'. Spot a 90 sx class "C" cement plug from 1252' to surface. This will fill the entire well bore up from the</li> </ol>		
CIBP to the surface. WOC and tag plug. 3. Cut off wellhead and install dry hole marker. Clean up location as per regulations.		
SEE ATTACHED	Notify OCD 24 hrs	
CONDITIONS OF	To any work do	
APPROVAL	to driv work do	NMOCD ARTESIA
· .	*	
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and cor	nplete to the best of my knowled	dge and belief.
4		
SIGNATURE	TITLE <u>Regulatory Complian</u>	ce Technician DATE June 13, 2011
Turne on mint name	adduaaa aatan Quataanatu	alour com DIONE, 575 749 4295
Type or print name <u>Craig Aton</u> E-n For State Use Only	ail address: <u>caton@yatespetr</u>	oleum.com PHONE: <u>575-748-4385</u>
ADDROVED DV JAKIA		
APPROVED BY:	TITLEApproval Granted (	DATE 6/20/20/





## NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 1301 W. GRAND AVENUE ARTESIA, NM 88210 (575)748-1283

## CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: Vates Petruleum Corp. Well Name & Number: Gissler AV #22 API #: 30-015-23480

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- **3.** Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- **4.** A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 5. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 6. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.

DG Date: <u>6/20/80//</u>