

Submit 1 Copy To Appropriate District  
Office  
District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Ave, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd, Aztec, NM 87410  
District IV  
1220 S St Francis Dr, Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
October 13, 2009

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-015-26040
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-2293
7. Lease Name or Unit Agreement Name Marbob State
8. Well Number 001
9. OGRID Number 18917
10. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other Administrative Order

2. Name of Operator Read & Stevens, Inc. #SWD-1266

3. Address of Operator P. O. Box 1518, Roswell, NM 88202-1518

4. Well Location

Unit Letter A : 660 feet from the North line and 660 feet from the East line  
Section 19 Township 19S Range 29E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)-  
3358' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: SWD Drill Out Plugs ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

06/09/2011 - 06/21/2011

MIRU. Tag plug 6' from surface. Drill out 20' cmt. Tag plug @ 80' FS. Drill out cmt down to 256' FS. Tag cmt @ 437', fell through plug @ 455'. Drill out plug from 1152'-1490'. Tag plug @ 1741' FS. Drill out plug from 1741'-2024' FS. Tag plug @ 2183'. Drill out plug to 2185'. Tag plug @ 2195' FS, fell through plug @ 2203'. Drill out plug from 2306' - 2409'. Drilled through plug @ 2409'. Drill through plug @ 2727'. Drill out plug from 2818' through 2820'. Drill through plug @ 2820'. Tag plug @ 2966' Rec cmt to surface. Drill through plug to 3585'. Tag plug @ 3585' FS, fell through @ 3592'. Tag plug @ 3655, fell through @ 3660'. Tag plug @ 3660', fell through @ 3740'. Circ hole clean. Prep to perf well.

Spud Date:

06/09/11 re-entry

Rig Release Date

Notify OCD 24 hrs . prior to  
any work done.

RECEIVED

JUN 24 2011

NMOCD ARTESIA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Will Palmer TITLE Manager, Production & Compl. DATE 06/23/2011

Type or print name Will Palmer E-mail address: wpalmer@read-stevens.com PHONE: 575-622-3770  
For State Use Only

APPROVED BY: Ruthie Inao TITLE Compliance Officer DATE 7/5/11  
Conditions of Approval (if any):

Notify OCD 24 hrs . prior to  
any work done.