		0	CD-ARTESI	1		
Form 3160-5 UNITED STATES					FORM APROVED	
(February 2005) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT					OMB NO. 1004-0135 EXPIRES: March 31, 2007	
SUNDRY NOTICES AND REPORTS ON WELLS					5. Lease Serial No.	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) tor such proposals					NMNM-0544986 6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE					1	
1a. Type of Well 🔽 Oil Well 🗌 Gas Well 🗌 Other					7. Unit or CA Agreement Name and No.	
					8 Well Name and No.	
2. Name of Operator DEVON ENERGY PRODUCTION COMPANY, LP					Aldabra 25 Federal 7H 9. API Well No.	
3. Address and Telephone No.					30-015-38603	
20 N. Broadway, Oklahoma City, Ok 73102-8260 405-235-3611					10. Field and Pool, or Exploratory	
Location of Well (Report location clearly and in accordance with Federal requirements)* 200 FSL 1000 FEL P SEC 25 T23S R31E					Upper Bone Spring 11. County or Parish State	
BHL: 330' FNL & 1000' FEL Unit A					Eddy NM	
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OS SUBMISSION	<u> </u>		TYPE	OF ACTION		
Notice of Intent	Acidize		Deepen Fracture Treat	Productio	on (Start/Resume)	Water Shut-Off
Subsequent Report	Casing Repair		New Construction			✓ Other Drilling
Final Abandonment Notice	Change Plans		Plug and Abandon	Tempora	irily Abandon	Operations
13 Describe Proposed or Completed Operations (Cli	early state all pertinent details,		Plug Back tates, including estimated d	Water Di ate of starting any		nate duration thereof If the proposal
Bond No on file with BLWBIA Required subsequent r a Form 3160-4 shall be filed once testing has been con site is ready for final inspection) 4/29/11 - MIRU & spud. 5/1/11 - TD 17 1/2" hole @ 988'. sx, Yld 14.8. Displ w/ FW. 45 bbl 5/2/11 - 5/3/11 - NU BOPS. Test 5/6/11 - 5/7/11 - TD 12 1/4" hole Lead w/ 1400 sx C, 2.04 cf/sx. Ta 5/8/11 - Test to 1285 psi, good. 1500 psi, good, held 10 mins. 5/22/11 - TD 8 3/4" hole @ 13,44 6011'. RU BJ PT lines 4400 psi. 1	npleted Final Abandonment N RIH w/ 24 jts 23 3 Is to surf. WOC. Rams 3000 psi, hig e @ 4529'. RIH w 1 ail w/ 300 sx C, 1.37 NU BOP. Test 250 00'. RIH w/ 173 jts	/8" 48# H-4 gh, 250 low, .00 jts 9 5/3 7 cf/sx. Circ psi low, 500 5 1/2" 17#	only after all requirement, co csg & set @ 98 test annular 150 3" 40# J-55 LTC c 151 bbls cmt to 00 psi high. Annu P-110 LTC csg &	ncluding reclamat 38'. MIRU B 50 high, 25d 5g & set @ 5urf. RD B Jar 250 ps 139 jts 17#	tion, have been completed, ar BJ lead w/ 695 sx, 0 low. Test to 12 4529'. RU BJ & P ⁻ J. WOC. i low, 2500 psi hig # P-110 BTC & set of	Yld 13.5. Tail w/ 250 10 psi, ok. T lines to 4000 psi. h, good. Test csg to @ 13,370'. DV @
WOC. 2nd stage: Lead w/ 200 sx Cl C and tail w/ 100 sx 60:40 C. Displ w/ 130 bbls wtr. Closed DV tool. No cmt to surf. Rlse rig @ 18:00.						
6/3/11 - Tag tbg @ 13,115'. CHC. PBTD 13,325'. Test csg 1500 psi, 15 mins, good. MIRU WL & run CBL. TOC @ 3250'.						
Signed Juck T	Amet	Name Title	Judy A. Barnett Regulatory Spe		– Date	6/27/2011
(This space for Federal or State Office us	;e)					
Approved by Conditions of approval, if any:	· · · · · · · · · · · · · · · · · · ·	Title			Date	,
- File 10 0 6.0 - 660tion 1001, milities it a chine for an	y person knowingly and matery		n its junsdiction			mento or representations to any matter
		*See Instru	ction on Reverse S	ide		
Accepted for record つしし てーストー		JUL	CEIVED 15 2011 D ARTESIA		JUL BUREAU OF I	FOR RECORD