Received 03/24/2020 - NMOCD

Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 20

В	Expires: Jar	nuary 31, 2018							
SUNDRY	5. Lease Serial No. NMNM23765								
Do not use the abandoned we	6. If Indian, Allottee or	Tribe Name							
SUBMIT IN	7. If Unit or CA/Agreement, Name and/or No.								
Type of Well Oil Well	8. Well Name and No. BUFFALO TRACE	1/36 W1OB FEDCOM 1F							
Name of Operator MEWBOURNE OIL COMPAN	9. API Well No. 30-015-46774-00)-X1							
3a. Address P O BOX 5270 HOBBS, NM 88241	o. (include area code) 93-5905 3-5905)	Field and Pool or Exploratory Area WOLFCAMP						
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description				11. County or Parish, St	tate			
Sec 1 T26S R29E SWSE 400 32.065395 N Lat, 103.934494	FSL 1630FEL	,			EDDY COUNTY, NM				
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA									
TYPE OF SUBMISSION		TYPE OF ACTION							
☑ Notice of Intent	☐ Acidize	□ Dee			ion (Start/Resume)	☐ Water Shut-Off			
Conhangement Barnet	☐ Alter Casing	☐ Hyo	raulic Fracturing	□ Reclama	ation	■ Well Integrity			
☐ Subsequent Report	□ Casing Repair	☐ Nev	v Construction	□ Recomp	olete	⊠ Other			
☐ Final Abandonment Notice	☐ Change Plans	Plu:	g and Abandon	Tempor	arily Abandon	Change to Original A PD			
	☐ Convert to Injection	☐ Plu	Plug Back		Disposal				
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Mewbourne Oil Company requests approval to make the following changes to the approved APD: 1) Replace 7" production csg with 7 5/8" 39# P110 csg & adjust cement design as detailed in the attachment. Please contact Andy Taylor with any questions.									
7 C - 1 C C C C C C C C C C C C C C C C C	Electronic Submission #5 For MEWBOUF mitted to AFMSS for proce	506635 verifie RNE OIL COM essing by PRI	d by the BLM Well PANY, sent to the SCILLA PEREZ or	I Information Carlsbad 03/15/2020	System (20PP1590SE)				
Name (Printed/Typed) ANDY TAY			Title ENGINE						
Signature (Electronic S	ubmission)		Date 03/10/20	020					
	THIS SPACE FO	R FEDERA	L OR STATE (OFFICE US	SE				
Approved By OLABODE AJIBOLA			TitlePETROLE	IM ENGINE	EP.	Date 03/18/2020			
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conductions.	Office Carlsbad		LI	1 00/10/2020					
Title 18 U.S.C. Section 1001 and Title 43 U States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a catatements or representations as	crime for any pe to any matter w	rson knowingly and		ke to any department or ag	gency of the United			

⁽Instructions on page 2)
*** BLM REVISED *** BLM REVISED *** BLM REVISED *** BLM REVISED ***

Revisions to Operator-Submitted EC Data for Sundry Notice #506635

Operator Submitted

BLM Revised (AFMSS)

Sundry Type:

APDCH

NOI

NMNM23765

APDCH NOI

NMNM23765

Agreement:

Operator:

Lease:

MEWBOURNE OIL COMPANY

PO BOX 5270 HOBBS, NM 88241 Ph: 575-393-5905

MEWBOURNE OIL COMPANY P O BOX 5270 HOBBS, NM 88241 Ph: 575.393.5905

Admin Contact:

JACKIE LATHAN AUTHORIZED REPRESENTATIVE E-Mail: jlathan@mewbourne.com

Ph: 575-393-5905

JACKIE LATHAN AUTHORIZED REPRESENTATIVE E-Mail: jlathan@mewbourne.com

Ph: 575-393-5905 Fx: 575-393-5905

Tech Contact:

ANDY TAYLOR **ENGINEER**

E-Mail: ataylor@mewbourne.com

Ph: 575-393-5905

ANDY TAYLOR ENGINEER E-Mail: ataylor@mewbourne.com

Ph: 575-441-8396

Location:

State: County:

NM EDDY

Field/Pool:

98220

NM EDDY

WOLFCAMP

Well/Facility:

BUFFALO TRACE 1/36 W10B FEDCOM 1H Sec 1 T26S R29E Mer NMP SWSE 400FSL 1630FEL

BUFFALO TRACE 1/36 W10B FEDCOM 1H Sec 1 T26S R29E SWSE 400FSL 1630FEL 32.065395 N Lat, 103.934494 W Lon

PECOS DISTRICT DRILLING CONDITIONS OF APPROVAL

OPERATOR'S NAME: | Mewbourne Oil Company

LEASE NO.: | NMNM023765

WELL NAME & NO.: Buffalo Trace 1/36 W1OB Fed Com 1H

SURFACE HOLE FOOTAGE: | 400'/S & 1630'/E **BOTTOM HOLE FOOTAGE** | 330'/N & 2310'/E

LOCATION: | Section 1, T.26 S., R.29 E., NMPM

COUNTY: Eddy County, New Mexico

COA

H2S	↑ Yes	€ No	
Potash	• None	○ Secretary	↑ R-111-P
Cave/Karst Potential	∩ Low	Medium	← High
Cave/Karst Potential	← Critical		
Variance	None	Flex Hose	Other
Wellhead	Conventional	Multibowl	← Both
Other	☐ 4 String Area	☐ Capitan Reef	□WIPP
Other	Fluid Filled	☐ Cement Squeeze	☐ Pilot Hole
Special Requirements	☐ Water Disposal	▼ COM	□ Unit

All Previous COAs Still Apply.

A. CASING

Casing Design:

- 1. The 13-3/8 inch surface casing shall be set at approximately 700 feet (a minimum of 70 feet (Eddy County) into the Rustler Anhydrite and above the salt) and cemented to the surface.
 - a. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with surface log readout will be used or a cement bond log shall be run to verify the top of the cement. Temperature survey will be run a minimum of six hours after pumping cement and ideally between 8-10 hours after completing the cement job.
 - b. Wait on cement (WOC) time for a primary cement job will be a minimum of **8** hours or 500 pounds compressive strength, whichever is greater. (This is to include the lead cement)
 - c. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours

- after bringing cement to surface or 500 pounds compressive strength, whichever is greater.
- d. If cement falls back, remedial cementing will be done prior to drilling out that string.
- 2. The 9-5/8 inch intermediate casing shall be set at approximately 3250 feet. The minimum required fill of cement behind the 9-5/8 inch intermediate casing is:
 - Cement to surface. If cement does not circulate see B.1.a, c-d above. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry due to cave/karst or potash.
 - ❖ In Medium Cave/Karst Areas if cement does not circulate to surface on the first two casing strings, the cement on the 3rd casing string must come to surface.
- 3. The minimum required fill of cement behind the 7 inch production casing is:

Option 1 (Single Stage):

- Cement should tie-back at least **200 feet** into previous casing string. Operator shall provide method of verification.
- Excess cement calculates to 1%, additional cement might be required.

Option 2:

Operator has proposed a DV tool, the depth may be adjusted as long as the cement is changed proportionally. The DV tool may be cancelled if cement circulates to surface on the first stage.

- b. First stage to DV tool: Cement to circulate. If cement does not circulate off the DV tool, contact the appropriate BLM office before proceeding with second stage cement job.
- c. Second stage above DV tool:
 - Cement should tie-back at least **200 feet** into previous casing string. Operator shall provide method of verification.
- 4. The minimum required fill of cement behind the 4-1/2 inch production liner is:
 - Cement should tie-back 100 feet into the previous casing. Operator shall provide method of verification.

B. PRESSURE CONTROL

- 1. Variance approved to use flex line from BOP to choke manifold. Manufacturer's specification to be readily available. No external damage to flex line. Flex line to be installed as straight as possible (no hard bends).'
- 2. Operator has proposed a multi-bowl wellhead assembly. This assembly will only be tested when installed on the surface casing. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be **5000** (**5M**) psi.
 - a. Wellhead shall be installed by manufacturer's representatives, submit documentation with subsequent sundry.
 - b. If the welding is performed by a third party, the manufacturer's representative shall monitor the temperature to verify that it does not exceed the maximum temperature of the seal.
 - c. Manufacturer representative shall install the test plug for the initial BOP test.
 - d. If the cement does not circulate and one inch operations would have been possible with a standard wellhead, the well head shall be cut off, cementing operations performed and another wellhead installed.
 - e. Whenever any seal subject to test pressure is broken, all the tests in OOGO2.III.A.2.i must be followed.

C. SPECIAL REQUIREMENT (S)

Communitization Agreement

- The operator will submit a Communitization Agreement to the Carlsbad Field Office, 620 E Greene St. Carlsbad, New Mexico 88220, at least 90 days before the anticipated date of first production from a well subject to a spacing order issued by the New Mexico Oil Conservation Division. The Communitization Agreement will include the signatures of all working interest owners in all Federal and Indian leases subject to the Communitization Agreement (i.e., operating rights owners and lessees of record), or certification that the operator has obtained the written signatures of all such owners and will make those signatures available to the BLM immediately upon request.
- If the operator does not comply with this condition of approval, the BLM may take enforcement actions that include, but are not limited to, those specified in 43 CFR 3163.1.
- In addition, the well sign shall include the surface and bottom hole lease numbers. When the Communitization Agreement number is known, it shall also be on the sign.

OTA03182020