Form 3160-5 (August 2007)

OCD-ARTESIA **UNITED STATES**

DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB No 1004-0137 Expires: July 31, 2010

5 Lease Serial No. LC - 070286

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

7 If Unit of CA/Agreement, Name and/or No SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well 8. Well Name and No. Oil Well Other Gas Well Federal 2 Name of Operator Hudson Oil Company of Texas 9 API Well No 30-015-04721 3a. Address 3b. Phone No. (include area code) 10 Field and Pool or Exploratory Area 616 Texas Street Dos Hermanos/Yates/Seven Rivers 817-336-7109 Fort Worth, Texas 76102 4 Location of Well (Footage, Sec., T., R, M., or Survey Description) 11 Country or Parish, State Eddy County, New Mexico 660' FNL & 1980' FWL, Unit C, Sec. 33, Township 20 South, Range 30 East 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Water Shut-Off Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Recomplete Other ✓ Subsequent Report Change Plans ✓ Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Dig out WH & Co. Weld 7" nipple on csg Pour cmt around WH 6/14/11 RIH to 1654' Spot 50 sx cmt POOH WOC RIH tag cmt @ 1547' POOH RIH W/ tbg to 1528' Spot 30 sx cmt 6/15/11 RIH tag cmt @ 1122' Drill out to 1320' to perf & squeeze PU bit & DC 6/16/11 RIH W/ bit & DC Tag cmt @ 1090' Drill to 1336' POOH Circ hole w/ 50 bbls H20 and gel 6/17/11 RIH W/ guns Perf @ 1310 POOH RIH W/ tbg to 1336' Spot 170 sx cmt POOH WOC RIH Tag cmt @ 419' POOH to 60' Perf @ 60' RIH W/ 6/20/11 2 its tbg Circ 15 sx class c cmt 6/21/11 Cut off WH & Install dry hole marker ACCEPTED FOR RECORD Accepted as to plugging of the well bore. Liability under bond is retained until Surface restoration is completed. AUG 1 7 2011 RECLAMATION DUE /2-/8-/
14 I hereby certify that the foregoing is true and correct Name (Printed/Typed) REAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE Tony Tucker Title Field Superintendent Date 07/20/2011 Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would Office entitle the applicant to conduct operations thereon Title 18 U S C Section 1001 and Title 43 U S C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

8/24/2011

Accepted for record NMOCD

