### Form 3160-5 (August 2007)

(Instructions on page 2)

## OCD-ARTESIA

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No 1004-0137
Expires. July 31, 2010

5. Lease Serial No. NM-67980

6. If Indian, Allottee or Tribe Name

## SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Hen Form 2160-2 (APD) for such proposals

abandoned well.	Jse Form 3160-3 (A	PD) for suc	h proposal	S.			
SUBMIT IN TRIPLICATE - Other instructions on page 2.					7. If Unit of CA/Agree	ment, Name and/or No.	
1. Type of Well  Oil Well  Gas W			8. Well Name and No. Santa Fe Federal #1				
2. Name of Operator RKI Exploration & Production, LLC.					9. API Well No. 3001525590		
3a. Address 3817 NW Expressway, Suite 950 Oklahoma City, Oklahoma 73112	3b. Phone No. (include area code) 405-996-5750			10. Field and Pool or Exploratory Area Delaware			
4. Location of Well (Footage, Sec., T., I	)			11. Country or Parish, State			
2080 FNL & 2080 FEL, Section 35, T 22 S , R. 28 E.					Eddy		
12. CHEC	K THE APPROPRIATE BO	X(ES) TO IND	CATE NATURI	E OF NOT	ICE, REPORT OR OTHE	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACT				TION		
Notice of Intent	Acidize Alter Casing	Deepe	en ire Treat	=	duction (Start/Resume)	Water Shut-Off Well Integrity	
Subsequent Report	Casing Repair	=	Construction	=	complete	Other Change of Operator	
Final Abandonment Notice	Change Plans Convert to Injection	Plug a	and Abandon Back		nporarily Abandon ter Disposal		
	ed operations. If the operations be added to the control of the co	on results in a mode filed only after operator from Frestrictions community of the NMOC	ultiple completion all requirements  Ray Westall to Forceming operations	RKI Exploions conditate Office	pletion in a new interval, g reclamation, have been ration & Production, LLC ucted on the leased land of the BLM.  APPR  FEB 1 /s/ JD W	a Form 3160-4 must be filed once completed and the operator has  C. and of NM-67980.	
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)  BARRY W. HUNT  Title AGENT FOR RKIE					EXPLORATION & PRO	ODUCTION LLC	
7				Extremely at the	700011011, 220.		
Signature $\int dn \omega$ , $\int dn = 6/23/2$				110			
	THIS SPACE	FOR FEDE	RAL OR ST	ATE OF	FICE USE		
Approved by				·		· · · · · · · · · · · · · · · · · · ·	
			Title		<u> </u>	Pate	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.							
Title 18 U.S C. Section 1001 and Title 43 fictitious or fraudulent statements or repre				nd willfully	to make to any department	t or agency of the United States any false	

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

### **Conditions of Approval**

#### RKI Exporation & Production, LLC. Santa Fe Federal NM67980

- 1. Tank battery must be bermed/diked (must be able to contain 1 1/2 times the volume of the largest tank).
- 2. Submit for approval of water disposal method.
- 3. Submit updated facility diagrams as per Onshore Order #3
- 4. This agency shall be notified of any spill or discharge as required by NTL-3A.
- 5. All outstanding environmental issue must be addressed within 90 days. Contact Jim Amos for inspection and to resolve environmental issues. 575-234-5909
- 6. Install legible well sign on location with operator name, well name and number, lease number, unit number, 1/4 1/4, section, township, and range. NMOCD requires the API number on well signs.
- 7. Subject to like approval by NMOCD.