
Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
Office District 1 – (575) 393-6161 RECEIVED y, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbl, NM 88240 <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 8821 MAR 2 8 2012 IL CONSERVATION DIVISION	WELL API NO. 30- 015-23469
811 S. First St., Artesia, NM 88210 A CONSER VALION DIVISION District III – (505) 334-6178 1220 South St. Francis Dr.	5. Indicate Type of Lease
District III – (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd, Azto MOOD ARTESIA Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S St Francis Dr., Santa Fe, NM 87505	B-8949
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	State CZ
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number
2. Name of Operator	9. OGRID Number
OXY USA WTP LP 3. Address of Operator	192463 10. Pool name or Wildcat
P.O. Box 50250 Midland, TX 79710	Turkey Track Morrow, N.
4. Well Location	
Unit Letter H: 2180 feet from the North line and Section 4 Township 195 Range 29 É	R60 feet from the <u>east</u> line NMPM County Eddy
11. Elevation (Show whether DR, RKB, RT, GR, etc.,	
3421 GR	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
	•
NOTICE OF INTENTION TO: SUB- PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	SEQUENT REPORT OF: K
TEMPORARILY ABANDON 🔼 CHANGE PLANS 🗌 COMMENCE DRI	LLING OPNS. P AND A
PULL OR ALTER CASING	ГЈОВ . 🔲
OTHER: OTHER: OTHER: OTHER: III	
	d give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Con	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion.	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Con	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. TD-11500' PBTD-11330' Perfs-11130-11325' ClBP-11330'(1991) OXY USA WTP LP respectfully requests to temporarily abandon this well.	npletions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. TD-11500' PBTD-11330' Perfs-11130-11325' CIBP-11330'(1991) 	npletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. TD-11500' PBTD-11330' Perfs-11130-11325' ClBP-11330'(1991) OXY USA WTP LP respectfully requests to temporarily abandon this well.	npletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. TD-11500' PBTD-11330' Perfs-11130-11325' CIBP-11330'(1991) OXY USA WTP LP respectfully requests to temporarily abandon this well. for possible Bone Spring recompletion.	npletions: Attach wellbore diagram of
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. TD-11500' PBTD-11330' Perfs-11130-11325' ClBP-11330'(1991) OXY USA WTP LP respectfully requests to temporarily abandon this well. for possible Bone Spring recompletion. 1. RIH & set CIBP @ +/-11080' 	npletions: Attach wellbore diagram of
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. TD-11500' PBTD-11330' Perfs-11130-11325' CIBP-11330'(1991) OXY USA WTP LP respectfully requests to temporarily abandon this well. for possible Bone Spring recompletion. 1. RIH & set CIBP @ +/-11080' 2. Notify NMOCD of casing integrity test 24hrs in advance. 3. RU pump truck, circulate well with treated water, pressure test casing integrity test 24hrs in advance. 	npletions: Attach wellbore diagram of It is currently being evaluated ng to 500# for 30 min. TA status may be granted after a
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. TD-11500' PBTD-11330' Perfs-11130-11325' CIBP-11330'(1991) OXY USA WTP LP respectfully requests to temporarily abandon this well. for possible Bone Spring recompletion. 1. RIH & set CIBP @ +/-11080' 2. Notify NMOCD of casing integrity test 24hrs in advance. 3. RU pump truck, circulate well with treated water, pressure test casing integrity test 24hrs in advance. 	It is currently being evaluated ng to 500# for 30 min. TA status may be granted after a successful MIT test is performed.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. TD-11500' PBTD-11330' Perfs-11130-11325' CIBP-11330'(1991) OXY USA WTP LP respectfully requests to temporarily abandon this well. for possible Bone Spring recompletion. 1. RIH & set CIBP @ +/-11080' 2. Notify NMOCD of casing integrity test 24hrs in advance. 3. RU pump truck, circulate well with treated water, pressure test casing spud Date: Rig Release Date:	It is currently being evaluated If the status may be granted after a successful MIT test is performed. Contact the OCD to schedule the test
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. TD-11500' PBTD-11330' Perfs-11130-11325' CIBP-11330'(1991) OXY USA WTP LP respectfully requests to temporarily abandon this well. for possible Bone Spring recompletion. 1. RIH & set CIBP @ +/-11080' 2. Notify NMOCD of casing integrity test 24hrs in advance. 3. RU pump truck, circulate well with treated water, pressure test casing spud Date: Rig Release Date:	It is currently being evaluated ng to 500# for 30 min. TA status may be granted after a successful MIT test is performed.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. TD-11500' PBTD-11330' Perfs-11130-11325' CIBP-11330'(1991) OXY USA WTP LP respectfully requests to temporarily abandon this well. for possible Bone Spring recompletion. 1. RIH & set CIBP @ +/-11080' 2. Notify NMOCD of casing integrity test 24hrs in advance. 3. RU pump truck, circulate well with treated water, pressure test casing spud Date: Rig Release Date:	It is currently being evaluated It is currently being evaluated It is status may be granted after a successful MIT test is performed. Contact the OCD to schedule the test is it may be witnessed.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. TD-11500' PBTD-11330' Perfs-11130-11325' CIBP-11330'(1991) OXY USA WTP LP respectfully requests to temporarily abandon this well. for possible Bone Spring recompletion. 1. RIH & set CIBP @ +/-11080' 2. Notify NMOCD of casing integrity test 24hrs in advance. 3. RU pump truck, circulate well with treated water, pressure test casing spud Date: Rig Release Date:	It is currently being evaluated It is currently being evaluated It is sometimes and the successful MIT test is performed. Contact the OCD to schedule the test is it may be witnessed.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. TD-11500' PBTD-11330' Perfs-11130-11325' CIBP-11330'(1991) OXY USA WTP LP respectfully requests to temporarily abandon this well. for possible Bone Spring recompletion. 1. RIH & set CIBP @ +/-11080' 2. Notify NMOCD of casing integrity test 24hrs in advance. 3. RU pump truck, circulate well with treated water, pressure test casing spud Date: Rig Release Date:	It is currently being evaluated It is currently being evaluated It is sometimes and the successful MIT test is performed. Contact the OCD to schedule the test is it may be witnessed.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. TD-11500' PBTD-11330' Perfs-11130-11325' CIBP-11330'(1991) OXY USA WTP LP respectfully requests to temporarily abandon this well. for possible Bone Spring recompletion. 1. RIH & set CIBP @ +/-11080' 2. Notify NMOCD of casing integrity test 24hrs in advance. 3. RU pump truck, circulate well with treated water, pressure test casing spud Date: Rig Release Date: Title Regulatory Advisor	It is currently being evaluated It is currently being evaluated
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. TD-11500' PBTD-11330' Perfs-11130-11325' CIBP-11330'(1991) OXY USA WTP LP respectfully requests to temporarily abandon this well. for possible Bone Spring recompletion. 1. RIH & set CIBP @ +/-11080' 2. Notify NMOCD of casing integrity test 24hrs in advance. 3. RU pump truck, circulate well with treated water, pressure test casing spud Date: Rig Release Date: Title Regulatory Advisor	It is currently being evaluated
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. TD-11500' PBTD-11330' Perfs-11130-11325' CIBP-11330'(1991) OXY USA WTP LP respectfully requests to temporarily abandon this well. for possible Bone Spring recompletion. 1. RIH & set CIBP @ +/-11080' 2. Notify NMOCD of casing integrity test 24hrs in advance. 3. RU pump truck, circulate well with treated water, pressure test casing spud Date: Rig Release Date: Rig Release Date: TITLE Regulatory Advisor Type or print nameDavid Stewart E-mail address: david_stewart@ox	It is currently being evaluated It is currently being evaluated

OXY USA WTP LP - Proposed State CZ #1 API No. 30-015-23469




CIBP @ 11080'

1991-CIBP @ 11330'

OVV HEA WITH LE - Curre

OXY USA WTP LP - Current State CZ #1 API No. 30-015-23469



1991-CIBP @ 11330'