

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO. 30-005-60164
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Double L Queen Unit
8. Well No. 004
9. Pool name or Wildcat Double L Queen; Assoc.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:
Oil Well ☐ Gas Well ☐ X Other

2. Name of Operator
Tipton Oil & Gas Acquisitions, Inc.

3. Address of Operator
P.O. Box 1234, Lovington, NM 88260

4. Well Location
Unit Letter E: _____ feet from the _____ line and _____ feet from the _____ line
Section 25 Township 14S Range 29E NMPM Chaves, County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

RECEIVED

MAR - 3 2004

OCD-ARTESIA

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: CONVERT INJECTOR TO PRODUCER ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Release tbg. from permanent packer. POOH with tbg. GIH with work string and bailer. Knock packer to bottom of hole.
POOH with work string and bailer. Run new rods, pump, and tbg. Set pumping unit and commence production.

NOI TO CONVERT - WORK NOT DONE *
PLEASE FIX TYPE TO "I."
THX - RICHARD
12/20/11

* INSPECTION VERIFIED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Debbi McKelvey TITLE Agent Secretary Treasurer DATE 2/27/04

Type or print name for Clay Tipton Telephone No. 505-631-4121
(This space for State use)

APPROVED BY [Signature] TITLE Wild Sep ID DATE MAR 4 2004
Conditions of approval, if any: