Form 3160 5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB No. 1004-0137 Expires. July 31, 2010

5. Lease Serial No.

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

				· · · · · · · · · · · · · · · · · · ·
SUBMIT IN TRIPLICATE – Other instructions on page 2.				A/Agreement, Name and/or No.
1. Type of Well			\sim \sim \sim \sim \sim	
Oil Well Gas W	Tell Other		8. Well Name	and No. Jackson 5 A - 1
2. Name of Operator			9. API Well N	o. 504332 Pool or Exploratory Area
3a. Address 3b. Phone No. (include area code)			•	_
12808 Lorien Way OKC OK7312 405.5735-5645 Grayb				Durg Jackson JR OS-by 71 Parish, State
_				
1980 F5L 1980 FL	UL 20, T195	KBOE	USA	<u> </u>
12. CHEC	K THE APPROPRIATE BOX(ES) TO INDICATE NATUR	E OF NOTICE, REPORT O	R OTHER DATA
TYPE OF SUBMISSION		TY	PE OF ACTION	
Notice of Intent	Acidize	Deepen	Production (Start/Res	sume) Water Shut-Off
	Alter Casing	Fracture Treat	Reclamation	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	Other
	Change Plans	Plug and Abandon	Temporarily Abandon	n
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	
150/0 NE	put this was acidize perd FEACIDI	clean ou	t.	tion within the net 9
Short deadline SEE ATTA				CHED FOR
	1 COST AC	Alled 05/09/200	CONDITION	VS OF APPROVAL
		cepted for record	:	RECEIVED
	cofully,			MAY 03 2012
14. I hereby certify that the foregoing is tr Name (Printed/Typed)	ue and correct	Title Par	Jaco	NMOCD ARTESIA
Kevin Don17	 	1410 1012		
Signature Avan		Date 4)	20-12	APPROVED
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by				MAY 1 2012
n .		Tıtle		Date M
Conditions of approval, if any, are attached		arrant or certify		WESLEY W. INGRAM
that the applicant holds legal or equitable to		e which would Office		PETROLEUM ENGINEER

Title 18 U S C Section 1001 and Title 43 U S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,

Grayburg Jackson 5A-1 30-015-04332 Asher Enterprises LTD Co. May 1, 2012 Conditions of Approval

- 1. Operator was instructed in the Incident of Non-Compliance (INC-12CD20I) to submit a plug and abandonment procedure. Operator has not submitted that document, which is the resolution to the INC and the assessment. The operator is given 90 days to commence plugging the well after the NOI to plug and abandon has been approved. This provides the operator time to perform other actions to return the well to producing in paying quantities. SUBMIT P&A PROCEDURE IMMEDIATELY. See 43 CFR 3163.1(a) and (4) for potential action.
- 2. This well has been in non-compliance for approximately 20 years.
- 3. OPERATOR SHALL COMMENCE WORK ON THE WELL BY MAY 25, 2012.
- 4. Surface disturbance beyond the originally approved pad must have prior approval.
- 5. Closed loop system required.
- 6. Operator to have H2S monitoring equipment on location.
- 7. A minimum of a 2,000 (2M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above precharge. The pre-charge test shall follow requirements in Onshore Order #2.
- 8. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 9. Operator shall perform a 72 hour independent well test using an independent tester acceptable to the BLM. This test to be performed by June 15, 2012. BLM to be notified a minimum of 24 hours prior to starting the test by calling 575-361-2822.
- 10. Operator to submit a sundry within 5 days after the well is returned to production.
- 11. Operator shall also submit a Subsequent Report sundry detailing by date all work completed. Include a current well bore diagram.
- 12. OPERATOR IS ALSO IN NON-COMPLIANCE ON THE UNIT AS THEY HAVE NOT SUBMITTED THE UNIT PLAN OF OPERATIONS THAT IS REQUIRED ON AN ANNUAL BASIS.

WWI 050112