

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

See revised C-141  
@ OCD ONLINE Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

nMLB 1215336744

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company BOPCO, L.P. 260737	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name: James Ranch Unit 48 Battery	Facility Type E&P

Surface Owner Federal	Mineral Owner Federal	Lease No. LC0300
-----------------------	-----------------------	------------------

LOCATION OF RELEASE NPE 30-015-27791

Unit Letter M	Section 12	Township 22S	Range 30E	Feet from the 990	North/South Line South	Feet from the 330	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude N 32.402308 Longitude W 103.842011

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 30 bbls produced water	Volume Recovered: 10 bbls
Source of Release: Water Transfer Pump	Date and Hour of Occurrence 4/20/12 Time unknown	Date and Hour of Discovery 4/20/12 11:30 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Emergency response #104	
By Whom? Tony Savoie	Date and Hour 4/20/12 12:19 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

RECEIVED  
MAY 04 2012  
NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.\* A 2" X 1 1/2" connection on the discharge of the water transfer pump broke. The connection and the associated piping were replaced.

Describe Area Affected and Cleanup Action Taken.\* An area covering approximately 2300 sq. ft inside the earthen containment around the tanks and pump were affected by the release along with approximately 200 sq. ft outside the containment area due to the spray from the broken fitting. All of the free standing liquid was recovered with a vacuum truck. A sampling event will be scheduled the week of 5/7/12 to determine the vertical extent of the release. The spill will be remediated following the NMOCD guidelines for spill remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by District Supervisor Signed By: [Signature]	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: JUN 01 2012	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/3/12 Phone: 432-556-8730	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 7/1/2012	

\* Attach Additional Sheets If Necessary

2RP-1142