Form 3160-5 (February 2005)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APROVED OMB NO 1004-0137 EXPIRES March 31, 2007

SUNDRY NOTICES AND REPORTS	ON WELLS OCD Artesia	5. Lease Senal No
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals		NMNM 97885
SUBMIT IN TRIPLICATE - Other instruc		To initialit, Allottee of Thibe Ivalitie
		7. Unit or CA Agreement Name and No
1 Type of Well Oil Well Gas Well Other SWD WELL		8 Well Name and No.
2 Name of Operator		CAMPANA 1
DEVON ENERGY PRODUCTION COMPANY, LP		9. API Well No.
3a, Address	3b. Phone No (include area code)	30-015-21098
333 West Sheridan Avenue, Oklahoma City, OK 73102-8260 405-552-4615		10. Field and Pool, or Exploratory Area
4 Location of Well (Footage, Sec , T , R , M., or Survey Description) 1980 FNL 660 FWL 6 T22S R31E		CABIN LAKE 11 County or Parish, State
		Eddy NM
12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA		
TYPE OS SUBMISSION TYPE OF ACTION		
Notice of Intent Acidize Alter Casing	Deepen Mroduc	tion (Start/Resume)   Water Shut-Off  Mation   Well Integrity
✓ Subsequent Report Casing Repai	r 🔲 New Construction 🔲 Recom	plete Other
Final Abandonment Notice Change Plans		prarily Abandon Disposal
13 Describe Proposed or Completed Operations (Clearly state all pertinent details	, and give pertinent dates, including estimated date of starting a	any proposed work and approximate duration thereof If the proposal
deepen directionally or recomplete honzontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new		
Interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection)		
WELLBORE PLUGGED & ABANDONED  1. 5/15/12. MIRU. POOH w/3-1/2" Injection tubing and packer from 5892'.  2. Run tubing & set CIBP @ 5920'. CIBP did not shut water flow off.  3. Per approval from Terry Wilson w/BLM, RIH & set CIBP @ 5848'.  4. Circulate wellbore w/9.5# mud.  5. Spot 25 sx cmt on CIBP @ 5848.  6. Spot 463 sx cmt @ 3750'. Tag TOC @ 2727'. (10-3/4" csg shoe @ 3698')  7. Spot 485 sx cmt @ 2727'. Tag TOC @ 1715'.  8. Spot 550 sx cmt @ 1715'. Tag TOC @ 618'.  9. Spot 258 sx cmt @ 618'. Tag TOC @ 20'. Top out w/10 sx cmt to surface. (13-3/8" csg shoe @ 545')  10. 6/29/12-cut wellhead off, set dry hole marker. Wellbore plugged & abandoned.  RECLAMATION  DUE /2-26-/2  Accepted as to plugging of the well bore. Liability under bond is retained until Surface restoration is completed.		
Name Ronnie Slack Title Operations Technician		
Signature RMML SIMM	Date 6/29/12	ACCEPTED FOR DECORE
THIS SPACE FOR FEDERAL OR STATE OFFICE USEUCEPTED FUR RECORD		
Approved by		
	Title	Date
Conditions of approval, if any are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct or operations thereon		BUREAU OF LAND MANAGEMENT

At 1/18/2012

representations as to any matter within its junsdiction

Accepted for record NMOCD

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212 make it a crime for any person knowingly and willfully to make to any department or a tency of the United States and Jaise Literature and the U.S.C. Section 1001 and Title 43 U.S.C. Section 1212 make it a crime for any person knowingly and willfully to make to any department or a tency of the United States and Jaise Literature and the U.S.C. Section 1001 and Title 43 U.S.C. Section 1001 and Title

