Form 3160-5 (March 2012)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB No 1004-0137 Expires October 31, 2014

5 Lease Serial No. NMLC 067849

6 If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

7. If Unit of CA/Agreement, Name and/or No SUBMIT IN TRIPLICATE - Other instructions on page 2. 1 Type of Well 8. Well Name and No TRIGG B FEDERAL #002 Oil Well Gas Well Other 9 API Well No. 30-015-32495 2 Name of Operator COG OPERATING LLC 3a. Address 550 W TEXAS AVENUE, SUITE 100 10 Field and Pool or Exploratory Area 3b. Phone No. (include area code) LOGAN DRAW; WOLFCAMP (GAS) 432-685-4332 4. Location of Well (Footage, Sec., T,R.,M., or Survey Description) 11. County or Parish, State Eddy County, NM M-34-17S-27E, 660 FSL & 660 FWL 12 CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Production (Start/Resume) Water Shut-Off Acıdıze Deepen Notice of Intent Fracture Treat Reclamation Well Integrity Alter Casing Other CHANGE OF Casing Repair New Construction Recomplete ✓ Subsequent Report **OPERATOR** Plug and Abandon Change Plans Temporarily Abandon Plug Back Water Disposal Final Abandonment Notice Convert to Injection 13 Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection) This is notification of Change of Operator on the above referenced well. COG Operating LLC, as new operator, accepts all applicable terms, conditions, stipulations and restrictions concerning operations conducted on this lease or portion of lease described. Bond Coverage: BLM Bond No. NMB000740; NMB000215 APPROVED Change of Operator Effective: 07-02-2012 AUG 2 2 2012 Former Operator: Three Rivers Operating Co., LLC AUG 1 8 2012 /s/ JD Whitlock J SEE ATTACHED FOR CONDITIONS OF APPROVAL BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE 14 I hereby certify that the foregoing is true and correct Name (Printed/Typed) Title VICE PRESIDENT OF TEXAS J. STEVE GUTHRIE 6-29-12 Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Conditions of approval, if any, are attached . Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Conditions of Approval

COG Operating LLC

August 18, 2012

- 1. Tank battery must be bermed/diked (must be able to contain 1 1/2 times the volume of the largest tank).
- 2. Submit for approval of water disposal method.
- 3. Submit updated facility diagrams as per Onshore Order #3
- 4. This agency shall be notified of any spill or discharge as required by NTL-3A.
- 5. All outstanding environmental issue must be addressed within 90 days. Contact Jim Amos for inspection and to resolve environmental issues. 575-234-5909
- 6. Install legible well sign on location with operator name, well name and number, lease number, unit number, 1/4 1/4, section, township, and range. NMOCD requires the API number on well signs.
- 7. Subject to like approval by NMOCD.
- 8. If well is not on production submit Notice of Intent to return well to production or to P&A within 30 days of approval of change of operator.