Submit 1 Copy To Appropriate District Office District I – (575) 393-6161 1625 N French Dr, Hobbs, NM 88240 District II – (575) 748-1283		Form C-103 Revised August 1, 2011
		WELL API NO. 30-005-64129
811 S First St, Artesia, NM 88210 OIL CON	S First St, Artesia, NM 88210 OIL CONSERVATION DIVISION	
District IV – (505) 476-3460 Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		LOVING 7 FEE
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator		8. Well Number 1H9. OGRID Number
Devon Energy Production Company, LP		6137
 Address of Operator 333 W. Sheridan Avenue, Oklahoma City, OK 73102 		10. Pool name or Wildcat 97791 Wildcat; Mississippian (Gas)
4. Well Location		
Unit Letter_G: 2500feet from theNorth line and1400feet from theEastline		
Section 7 Township 10S Range 29E NMPM Chaves, County, NM 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3899' KB; 3879' GL		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
TEMPORARILY ABANDON CHANGE PLAN PULL OR ALTER CASING MULTIPLE COM	S 🗌 COMMENCE DR	TJUDIN OCD 24 hrs prior
	_	T JOINT OCD 24 hrs. prior To any work done.
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
MIRU. POOH w/2-3/8," production tubing from 8,004'.		
Pock 2. Set comment retainer in 7" casing @ 7,300'. Pump 70 sx comment below retainer down to top perforation @ 8,290'. (Open perfs from 8,290' to 11,026') $Woc Tos$		
7.5 from 8,290' to 11,026') $1.53. Cap cement retainer w/25 sx cement. (CTOC @ 7,140'. 4-1/2'' liner top @ 7,349.)$		
 Circulate wellbore w/9 ppg mud. Spot 30 sx cement @ 6,535'. (CTOC @ 6,345'. 9-5/8" shoe @ 6,485'. DV tool @ 6,458') - Woc Tag 		
6. Cut 7" casing (a) 4,450'. POOH w/casing. Spot 40 sx stub plug (a) 4,500'. Tag TOC. (CTOC (a) $4,350'$) - 7 a 5.		
 Spot 35 sx cement @ 3,550'. (CTOC @ 3,440'. DV Tool @ 3,500'.) - Tas Spot 35 sx cement @ 2,265'. Tag TOC. (CTOC @ 2,157'. 13-3/8" shoe @ 2,215') - Tas 		
9. Spot 35 sx cement @ 870'. (CTOC @ 762'. B. Salt @ 870') $- Tas$		
10. Spot 35 sx cement @ 535'. (CTOC @ 427'. T 11. Spot 35 sx cement from 108' to surface.	. Salt @ 535') – Tag	
12. Cut wellhead off and set dry hole marker.		NMOCD ARTESIA
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE Romie Stack		
Type or print name _Ronnie Slack E-mail address: _Ronnie.Slack@dvn.com PHONE: _405-552-4615		
For State Use Only		
APPROVED BY: The TITLE		
Conditions of Approval (if any); is complete by 1/18/2013		
	/	

A

.





NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

Operator: <u>Devon Energy Production Co., LP</u> Well Name & Number: <u>LOVING 7 FEE #1H</u> API #: 30-005-64129

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.

8. Cement Retainers may not be used.

9. Squeeze pressures not to exceed 500 psi., unless approval is given by NMOCD Plugging Supervisor.

.

- 10. Plugs may be combined after consulting with NMOCD P & A Supervisor.
- 11. Minimum WOC time for tag plugs will be 4 hrs.

DG DG Date: <u>10/18/12</u>