Form 3160-5 (September 2001)

UNITED STATES Cons. DIV-Dist. 2
DEPARTMENT 30 THVV TO GRAND MANAGEMENT

SUNDRY NOTICES AND REPORTS

FORM APPROVED OMB No. 1004-0135 Expires: January 31, 2004

Lease Serial No.		
NM 7724	 	

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE- Other ins	tructions or	reverse side.	7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well . Gas Well Other			8. Well Name and No.	
2. Name of Operator Edge Petroleum Oper. Co., Inc. 3a. Address 3b. Phone No. (include area code)		Henshaw 7 Federal #1 9. API Well No. 30-015-32676		
3a. Address 1301 Travis, Suite 2000 Houston, TX	3b. Phone No. (include area code) 713-427-8883		10. Field and Pool, or Exploratory Area WC Henshaw; Upper Penn 11. County or Parish, State Eddy, New Mexico	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1320' FWL & 1110' FSL of Sec. 7, T-16S, R-30E				
12. CHECK APPROPRIATE BOX(ES) T	O INDICATE	NATURE OF NOTICE,	REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION			
Subsequent Report Subsequent Report Final Abandonment Notice Casing Repair Change Plans Convert to Injection Attach the Bond under which the work will be performed or prefollowing completion of the involved operations. If the operative testing has been completed. Final Abandonment Notices shall determined that the site is ready for final inspection.) The Henshaw 7 Federal #1 was plugged back and test 1. Set a 4 1/2" CIBP @ 4200' and dumped 35' of ceme	ally, give subsurfa ovide the Bond No on results in a mult be filed only after a ed the 2200' inte	truction Recomplete bandon Temporarily a Water Dispose uding estimated starting date of ce locations and measured and on file with BLM/BIA. Requirely completion or recompletion all requirements, including recla	Abandon al Carry Proposed work and approximate duration thereof. true vertical depths of all pertinent markers and sones. tired subsequent reports shall be fried within 30 days in a new carryal, a Form 3160-4 shall be filled once	
 Cut 4 1/2" casing @ 3920' and set a 150' cement plug (45 sx) above casing stub. Tagged cemen Set a 9 5/8" CIBP @ 2900' and dumped 35' of cement on top. PBTD 2865'. Perforated from 2178' to 2195' 4 SPF. Acidized with 3000 gallons 15% HCl. Swab tested, no shows. Plans are now to plug and abandon as follows: Set 9 5/8" CIBP @ 2150' with 35' of cement on top. Circulate hole with 9# mud. Set 100' cement plug from 525' to 425'. (Surface casing shoe @ 475') Set 60' cement plug at surface. 		APPROVED JUN - 3 2005 LES BABYAK PETROLEUM ENGINEER		
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)				
Amanda Simmons		Title Production Assistant		
		_		

THIS SPACE FOR FEDERAL OR STATE OFFICE USE Date Approved by Title NMOCD Conditions of approval, if any, are attached. Approval of this notice does not warrant or APPROVAL SUBJECT TO certify that the applicant holds legal or equitable title to those rights in the subject become which would entitle the applicant to conduct operations thereon. Office GENERAL REQUIREMENTS AND

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully and a figure and