NWOCD

Form 3160-5 (April 2004)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OM B No. 1004-0137
Expires: March 31, 200
Englison March 51, 200

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

. Lease Serial No.	
M-57273	
If Indian Allottee or Tribe Name	

SUBMIT IN TR	7. If Office of CAPAgreeniciti, Name and of No.			
1. Type of Well  Cil Well	Gas Well Other	• • •	0 5 2005	8. Well Name and No.
2. Name of Operator Pogo	Palladium 7 Federal #10 9. APIWellNo.			
3a. Address		3b. Phone No. (include area code)		30-015-33969
P.O. Box 10340,	Midland, TX	432-685-810	00	10. Field and Pool, or Exploratory Area
4. Location of Well (Foolage, Sec.,	T., R., M., or Survey Description)			Sand Dunes Delaware South 11. County or Parish, State
990' FSL & 1650'	C OF MOTION B	Eddy County, NM		
12. CHECK AI	PPROFRIATE BOX(ES) TO	INDICATE NATURE	OF NOTICE, K	EPORT, OR OTHER DATA
TYPE OF SUBMISSION		TYPE	E OF ACTION	
Notice of Intent  Subsequent Report  Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Statement of Statement of Statem	Well Integrity  X Other Spud
12 Describe Proposed or Complete	tad Operation (clearly state all pertir	nent details including estima	ated starting data of m	re proposed work and approximate direction than of

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Spud & Set Surface Csg – MIRU Capstar #9. Spud well @ 0:30 hrs 06/01/05. Drld 17-1/2" hole to 1005'. TD reached @ 16:00 hrs 06/02/05. Ran 24 jts 13-3/8" 54.5#, ST&C csg. Cmt'd w/ 600 sks Cl C 65:35 POZ @ 12.8 ppg followed by 200 sks Cl "C" + 2% CaCl2 @ 14.8 ppg. Cmt did not circ. WOC. Ran temp survey. TOC 60' FS. Pump 50 sks C Neat. Circ 10 sks to surface. Make cut-off. Weld on WH. NU BOP's & test to 1500# ok.

			100	EPTED FOR RECORD				
			Γ					
				JUN 2 9 2005				
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	1			DYAK				
Cathy Wright		Sr.Eng Tech		LES BABYAK PETROLEUM ENGINEER				
Signature Cathy Ully Ut	Date	06/16/05		PETROLLS				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved by		Title		Date				
Conditions of approval, if any, are attached. Approval of this notice does not warra								
certify that the applicant holds legal or equitable title to those rights in the subject le which would entitle the applicant to conduct operations thereon.	Office							
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.								

(Instructions on page 2)