1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S, First St., Artesia, NM 88210

Printed name: NM Youn

E-mail Address: nmyoung@mewbourne.com

Phone: 575-393-5905

Title: District Manager

Date:

Phone; (575) 748-1283 Fax: (575) 748-9720 District III 1000 Rio Brazos Road, Aztec, NM 87410

Phone: (505) 334-6178 Fax: (505) 334-6170 District IV 1220 S St. Francis Dr. Santa Fe. NM 87505

State of New Mexico

Form C-101 Revised November 14, 2012

Energy Minerals and Natural Resources RECEIVED **Ø**il Conservation Division

APR 19 2013

\$220 South St. Francis Dr.

Santa Fe NM 87505

☐AMENDED REPORT

Expiration Date: 4/23/2015

Phone: (505) 476-	3460 Fax: (505	5) 476-3462	MMOCD Y	ARTESIA	Santa Pe	, 141VI (37303				
APPLI	CATIC	N FOR	PERMIT T	O DRILL,	RE-ENTE	CR, DF	EEPEN, I	PLUGBAC	K, OR A	DD A ZONE	
		·	. Operator Name a						² OGRID Ni	mber	
	M	lewbourne Oil	Company	!	14744						
PO Box 5270 Hobbs, NM 88240						³ API Number					
,								30-0 15 -	Z 800	Well No.	
	erty Code	7	17		Property Name	State			well No.		
					rface Locati					7	
UL - Lot	Section	Township	Range	Lot Idn	Feet from	-	/S Line	Feet From	E/W Line	County	
I	2.	2.55	28.5		1980		140	0ماما	EACT	Eddu	
-				* Propose	ed Bottom H				P)	
UL - Lot	Section	Township	Range	Lot Idn	Feet from	N	/S Line	Feet From	E/W Line	County .	
					!						
	L, ,	l		9. P o	ool Informati	on.					
				Pool	Name 1					Pool Code	
	<u>\dill</u>	<u>ow Lal</u>	Ce. Dola	ware &	<i>ا</i> یاد				· · · · · · · · · · · · · · · · · · ·	96855	
	Additional Well Information										
	rk Type		12. Well Type		13. Cable/Rotary	, , , , ,					
	LE ultiple		17. Proposed Depth		18. Formation	tion 29 A 6					
	uitipie		6300							KSAP	
Depth to Grou	ınd water	40'	Distar	nce from nearest l	fresh water well						
			21.	Proposed Ca	sing and Cer	nent Pr	ogram				
Туре	Hole	e Size	Casing Size	Casing We	ight/ft	Setting Depth Sacks of			Cement Estimated TOC		
Sur face		<u>.</u> ገሬ`	133/8	48	Ħ	550		425 (Flace)		Sur face	
Intern	. '	u"	g 5/g		328	2561		1 /1	Flace	Sux face	
Probue	tien	77/8	5/2	17"		63	ου'		PIACE)	Surface	
Casing/Cement Program: Additional Comments											
This well was Drilled to 6603' \$ 5'2 Cag Ran to 6600' CIBP & Comente 6300' PBTD											
22. Proposed Blowout Prevention Program											
Type Working Pressure						Test Pressure			Manufacturer		
71/6-3	000 Doi	ble Rom		1500			1500			Shaffer	
										•	
^{23.} I hereby certify that the information given above is true and complete to the best of my knowledge and belief.						OIL CONSERVATION DIVISION					
I further certify that I have complied with 19.15.14.9 (A) NMAC 🗌 and/or						Approved By: Oa A					
19.15.14.9 (B) NMAC ⊠, if applicable. Signature:							KRI	Jack			

Approved Date: 4

Conditions of Approval Attached

District I PO Box 1980, Hobbs, NM 88241-1980 District II PO Drawer DD, Artesia, NM 88211-0719 District III 1000 Rio Brazze Rd., Aztoc, NM 87410 District IV

PO Box 2088, Santa Fe, NM 87504-2088

State of New Mexico

Energy, Minerals & Natural Resources Department

OIL CONSERVATION DIVISION PO Box 2088 Santa Fe, NM 87504-2088

Form C-102 Revised February 10, 1994 Instructions on back Submit to Appropriate District Office
State Lease - 4 Copies
Fee Lease - 3 Copies

AMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT										
1	Number 5-280	υŻ		1 Pool Cod	55	<i>ل</i> واز ۱۱هپ	Laker Laker		1876	"SVI
3983	7	HOS	s B	1414	State	Name			'.W	ell Number
OGRID No.	: l'		• 1	1	* Operator	Name				Ekryation
14742	<u> </u>	Mewbourne Oil Company						1		946
10 Surface Location										
UL or let no. S	11.	qideawo	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West	· ;	County
L_IL	2	25S	28E	77-1	1980	SOUTH f Different Fro	660	EAS	T	EDDY
UL or lot no. S	oction To	waship		Lot Ida	Feet from the	North/South Enc		Limitaria i		.64 at.
OL OF HOL 190.	ecusa 11	wrawib	Range	Torida	reat from the	North/South line	Feet from the	East/West	line	County
Dodicated Acres	¹³ loint or I	ofili ''' (Consolidatio	n Code U:C	Order No.	<u> </u>	:	<u>l:</u>	á	
40	J	·	COMPONIUM.		Jide ito.					
	BLE WII	L BE	ASSIGNE	D TO TH	IS COMPLETION	ON UNTIL ALL	INTERESTS H	AVE BEE	N CON	SOLIDATED
						EN APPROVED				
16							17 OPEI	RATOR	CERT	FICATION
					1					onsained herein is
•	-			- 1	Į.		True and com	piele to tre b	eat of my to	iomledge and occur.
										i i
	1				ľ			I AA .	fi.	:
							_ = 4/-	///- Ui	ul	1
						21 21 21 21	5.2-2	17	<u>ک.</u>	·
1.				·	-		<u> </u>	$M \cdot \lambda c$	DAIN	(
	1						Dist	rict	Mari	Ages
	-						Till	110	3.20	ر يا
							Date Date	<u> </u>	<u>, 20</u>	<u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>
1 100							11CIID1	/EVOP	വടമന	FICATION
							H .			Shown on this plai :
-							was plotted)	rom field note	es of acrual	surveys made by
						9 66C		my supervision of the best of		the same it mie
	ľ					1	JUNE	10-199	X	
	Į:					V.	Date of Sur	FYN R. R.E	00.	
							Signature &	Seal of Pro	Concent Su	Never.

COMPLETION PROCEDURE

Submitted By: N. Thompson

Wellname:	Hoss BHK State #1		
Location:	1980' FSL & 660' FEL Sec 2, T25S, R28E Eddy Co, NM		
Date:	4/18/2013		
Csg Set:	6600'	Packer Type:	NA
PBTD:		Packer Depth:	NA
Csg Size:	5-1/2" 17# J-55	Min ID:	2.205"
Tbg Size:	2-7/8" 6.5# N-80	Existing Perfs:	4626' – 5918
DV Tool:	5187'	New Perfs:	

Procedure:

- 1) Blade & caliche location. Set anchors. Start battery construction.
- 2) Dig out cellar. Remove dry hole marker. Weld on 8 5/8" 3K starting head on 8 5/8" 24# J55 intermediate csg. NU 8 5/8" x 7 1/16" 3K spool. NU 3k manual BOP.
- 3) Make up 4 3/4" MT bit and XO to 3 1/4" DC.
- 4) MIRU reverse pump and swivel.
- 5) Reverse drill out surface 60' cmt plug. Continue RIH w/6 3 1/4" DC's & 2 7/8" tbg to estimated top of next plug @ 500'. Test hole to 500#. Drill 100' cmt plug and circulate well clean.
- 6) RIH w/2 7/8" tbg to next cmt plug top @ +/-2511. Test hole to 500#. Drill approximately 100' of cmt. Circulate hole clean.
- 7) RIH w/2 7/8" tbg to next cmt plug top @ +/-4576. Test hole to 500#. Drill approximately 35' of cmt & Cast Iron Bridge Plug. Circulate hole clean.
- 8) RIH & tag PBTD @ 6135'. Circulate well clean. Test csg to 500#. POOH.
- 9) RIH w/production tbg. Set EOT @ +/-6000'. ND BOP. NU wellhead.
- 10) RIH w/pump & rods.
- 11) MI & set 320D-256-120 pumping unit w/gas engine.
- 12) PWOL for production.

Well Name: Hoss BHK State #1

Current Wellbore Diagram Updated by: N. Thom; Date Updated: 4/18/13 15 sx plug, 60' to surface 17 1/2" x 13 3/8" Set @ 550' 25 sx plug, 500' to 600" Cement to surface: -5 1/2" csg splice @ 2100', 300 sx cement 11" x 8 %" Set @ 2561' -25 sx plug, 2511' to 2611' Cement to surface: yes CIBP @ 4576' w/35' cement 0 -0 Perfs: 4626' - 4895' 0. Perfs: 4900' - 4990' Ō DV Tool @ 5187' Perfs: 5470' - 5740' -0 0 Perfs: 5912' - 5918' 0. CIBP @ 6170' w/35' cement 0 Perfs: 6216' - 6230' 0 CIBP @ 6370' w/35' cement ∦0<u>*</u> - Perfs: 6406' - 6484' Ö.

7 7/8" x 5 1/2"

Set @ 6600' PBTD @ 6603'

Perfs: 6406' - 6484'

0

7 7/8" x 5 1/2"

Set @ 6600' PBTD @ 6603'