Form 3160-5
Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

D.	UREAU OF LAND MANAGEN	AENIT		Expire	S. July 51, 2010			
SUNDRY NOTICES AND REPORTS ON WELLS					5. Lease Serial No. NMNM97113			
Do not use th abandoned we	6. If Indian, Allottee or Tribe Name							
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.			
Type of Well Oil Well	her			8. Well Name and No HOT SEAT FED				
Name of Operator COG OPERATING LLC	Contact: BRI E-Mail: bmaiorino@cor	AN MAIORINO ncho.com		9. API Well No. 30-015-35776				
3a. Address ONE CONCHO CENTER 600 MIDLAND, TX 79701		Phone No. (include area code) : 432-221-0467		10. Field and Pool, or Exploratory BONE SPRING				
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)	RECEIVE	D	11. County or Parish	i, and State			
Sec 35 T24S R25E NENE 99	0FNL 660FEL	APR 19 2013	1	EDDY COUNTY, NM				
12. CHECK APPI	ROPRIATE BOX(ES) TO IN	DIMMOXDUABJE	SOALCE,	REPORT, OR OTHI	ER DATA			
TYPE OF SUBMISSION		TYPE OF	ACTION					
■ Notice of Intent	☐ Acidize	☐ Deepen	☐ Produ	ction (Start/Resume)	■ Water Shut	-Off		
_	☐ Alter Casing	☐ Fracture Treat	□ Recla	mation	■ Well Integr	ity		
. Subsequent Report	☐ Casing Repair	■ New Construction	🗷 Recor	nplete	Other			
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	□ Temp	orarily Abandon				
	☐ Convert to Injection	□ Plug Back	■ Water	Disposal				
13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for final	ally or recomplete horizontally, give it will be performed or provide the E l operations. If the operation results pandonment Notices shall be filed on inal inspection.)	subsurface locations and measu Bond No. on file with BLM/BIA in a multiple completion or reco ly after all requirements, includ	red and true Required mpletion in ing reclamat	vertical depths of all perts subsequent reports shall b a new interval, a Form 31 ion, have been completed	inent markers and zo be filed within 30 day 160-4 shall be filed o	nes. /s nce		
COG Operating LLC respectfu	Illy request to abandon the Mo	orrow and recomplete in the	he Bone S	Spring.				
MIRU Kill well if necessary. Install back pressure valve. Remove wellhead & install BC Attempt to release from on/off	P.	Dode 4/34/13 Middle for record Middle for record h hole in tubing, and if ne	· cessarý,	SUBJECT T APPROVAL				
cut off) Pull tubing and visually inspec TIH with tubing open ended Spot Class H cement mixed a Circulate well clean	t 16.4# gal from 11190 ? 1100	_		E ATTACHED ONDITIONS O		AL		
14. I hereby certify that the foregoing is	Electronic Submission #2017	ATING LLC, sent to the Ca	arisbad					
Name(Printed/Typed) BRIAN MA	AIORINO	Title AUTHO	RIZED RE	PRESENTATIVE				
Signature (Electronic S	Submission)	Date 03/18/20	013	_APPR(OVED]		
	THIS SPACE FOR F	EDERAL OR STATE	OFFICE	USE				
Approved By		Title		APR	2018			
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	itable title to those rights in the subj			BUREAU OF LAND CARLSBAD FIE	MANAGEME NT LD OFFICE	P		
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it a crime	for any person knowingly and	willfully to	make to any department o	or agency of the Unit	ed		

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **
Novide C102 to NMOCA

Additional data for EC transaction #201787 that would not fit on the form

32. Additional remarks, continued

Spot Class H cement mixed at 16.4# gal from 8500 ? 8320 (Top of Wolfcamp @ 8414?) Circulate well clean Pressure test casing to 8000 psi Pressure test casing to 8000 psi
Perforate 3rd Bone Spring @ 8030? (10 holes), 7980? (14 holes) and 7930? (16 holes) w/6 spf, 600
phasing utilizing Halliburton cased hole log dated 3/23/04.

TIH w/tubing & packer. Spot acid across perfs. Set packer at 7850?

Acidize zone with 3000 gallons 15% HCI at 3 ? 5 BPM

Shut-in 1 hour & flow back

Pull tubing and packer

Set frac valve & prepare for frac.

Frac well utilizing attached procedure.

Set no flow composit plug at 6500?

Perforate 1st Bone Spring @ 6395? (16 holes), 6350? (14 holes), 6300? (10 holes) w/6 spf, 600
phasing utilizing Halliburton cased hole log dated 3/23/04

phasing utilizing Halliburton cased hole log dated 3/23/04 Frac well utilizing attached procedure. Set no flow composit plug at 6170?

Perforate 1st Bone Spring @ 6100? (12 holes), 6055? (10 holes), 6004? (10 holes) and 5956? (8 holes) w/6 spf, 600 phasing utilizing Halliburton cased hole log dated 3/23/04

Frac well Shut-in well for 24 hours

Flow well back until dead.

TIH with tubing and drill out plugs. TOH
TIH with tubing & rods.
Set pumping unit with gas engine if electrical power is not nearby

Place well on test

Current

Author:	Stroup		
Well Name	Hot Seat Fed	Well No.	#2
Field	Chosa Draw	API#:	30-015-35776
County	Eddy	Prop #:	
State	New Mexico	Zone:	Morrow
Date	2/19/2013		
GL	3594'		
KB	3611'		

Description	O.D.	Grade	Weight	Depth	Cmt Sx	TOC
Surface Csg	13 3/8	H40	48	237	300	Surface
Inter Csg	9 5/8	J55	36	1,505	650	Surface
Prod Csg	5 1/2	P110	17	11,870	4,040	540'
Liner						

Bullhead squeeze 5 1/2"-9 5/8" annulus w/1300sx

TOC @ 540'

17-1/2" Hole

13-3/8" (H40 - 48#) @ 237' w/300 sx TOC @ surface

2-3/8" L80 Tbg - 343 jts

TOC @ 1300'

12 1/4" hole

9-5/8" (J55 - 36#) @ 1505' w/650 sx TOC @ surface

DV Tool @ 8516' w/1925' sx

5 1/2" PLT Packer @ 11085' w/1.875" Profile Baker 1.81" R Nipple w/1.76" NG below packer

11124-11129

CIBP @ 11200' w/cmt

11214-11216, 11279-11282, 11292-11297

CIBP @ 11375' w/cmt

Morrow

11403 - 11436'

Cmt Retainer @ 11455' w/150 sx

11478-11490 & 11494-11497

8-3/4" hole


5-1/2" (P110 - 17#) @ 11870' w/815 sx

TD @ 11900'

Proposed

Author: Stroup Well Name **Hot Seat Fed** Well No. #2 Field Chosa Draw API#: 30-015-35776 County Eddy Prop #: State New Mexico Zone: Morrow Date 2/19/2013 GL 3594' KВ

Description	O.D.	Grade	Weight	Depth	Cmt Sx	тос
Surface Csg	13 [.] 3/8	H40	48	237	300	Surface
Inter Csg	9 5/8	J55	36	1,505	650	Surface
Prod Csg	5 1/2	P110	17	11,870	4,040	540'
Liner						



Bullhead squeeze 5 1/2"-9 5/8" annulus w/1300sx

TOC @ 540'

17-1/2" Hole

13-3/8" (H40 - 48#) @ 237' w/300 sx TOC @ surface

2-3/8" L80 Tbg - 343 jts

TOC @ 1300'

12 1/4" hole

9-5/8" (J55 - 36#) @ 1505' w/650 sx TOC @ surface

5956-6395 1st Bone Spring

6684-6756 2nd Bone Spring

7930-8030 3Rd Bone Spring

Cmt 8320-8500

DV Tool @ 8516' w/1925' sx

Cmt 11000-11190 11124-11129

CIBP @ 11200' w/cmt

11214-11216, 11279-11282, 11292-11297

CIBP @ 11375' w/cmt

Morrow

11403 - 11436'

Cmt Retainer @ 11455' w/150 sx

11478-11490 & 11494-11497

8 3/4" hole

5-1/2" (P110 - 17#) @ 11870' w/815 sx

TD @ 11900'

Hot Seat Federal Com 2 30-015-35776 COG Operating LLC April 15, 2013 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by July 15, 2013.

- 1. Surface disturbance beyond the originally approved pad must have prior approval.
- 2. Closed loop system required.
- 3. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 4. Operator to have H2S monitoring equipment on location.
- 5. A minimum of a 3000 (3M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 6. The operator shall tag CIBP at 11200'. Dump bail 210' of neat class H cement on top. Tag required.
- 7. Operator shall place a balanced cement plug of neat class H cement from 8500'-8320' to seal off the Wolfcamp formation. Tag required.
- 8. Prior to recompletion work, operator shall pressure test casing to 8,000 psi as proposed by operator. Submit results to the BLM.
- 9. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.

10. Subsequent sundry required detailing work done and completion report for the new formation. Operator to include well bore schematic of current well condition when work is complete.

JAM 041513