Submit I Copy To Appropriate District	State of New Me	xico		Form C-103	
District 1 - (575) 393-6161	Energy, Minerals and Natural Resources		Revised August 1, 2011		
Office District I - (575) 393-6161 Energy, Minerals and Natural Resources District II - (575) 748-1283 S11 S. First St., Artesia, NM 88210 MAY District III - (505) 334-6178 District III - (505) 334-6178 District III - (505) 334-6178 District III - (505) 344-6178 District III - (505) 374-6178 District III		WELL API NO.			
811 S. First St., Artesia, NM 88210 MAY	003 Rio Brazos Rd., Aztea NM 87410 000 Rio Brazos Rd., Aztea NM 87410		30-015-20200		
District III - (505) 334-61/8 "A" 06	2012 12 2 0 South St. Fran	icis Dr.	5. Indicate Type of Lease STATE X FEE		
1000 Rio Brazos Rd., Azteca NM 87410 District IV = (505) 476-3460 MOO	District IV – (505) 334-6178 District IV – (505) 476-3460 MOCD 1220 S. St. Francis Dr., Santa Fe, NM ARTESIA 1220 South St. Francis Dr. Santa Fe, NM 87505		6. State Oil & Gas		
1220 S. St. Francis Dr., Santa Fe, NM ARTES		E-997	i Lease IVO.		
				**	.
SUNDRY NOTICES (DO NOT USE THIS FORM FOR PROPOSALS	S AND REPORTS ON WELLS		7. Lease Name or Eddy BD State	Unit Agreement N	lame
DIFFERENT RESERVOIR. USE "APPLICATION OF THE PROPERTY OF THE P			Eddy BD State		
PROPOSALS.)		8. Well Number 001			
1. Type of Well: Oil Well Gas Well Other				·	
2. Name of Operator			9. OGRID Number 13645		
Lynx Petroleum Consultants, Inc. 3. Address of Operator			10. Pool name or Wildcat		
P.O. Box 1708, Hobbs, NM 88241			WC-015G-07 S203033P;B.S.		
4. Well Location					
	O Cost Costs the Costs	1: d 000	£ £	David No. 1	
Unit Letter P: 66		line and990	feet from the		
Section 32	Township 20S	Range 30E	NMPM	Eddy Coun	ty
11	. Elevation (Show whether DR,	KKB, KI, GK, etc.)			
12 Charle Appropriate Pay to In	digeta Natura of Nation P	anart or Other D	oto.		
12. Check Appropriate Box to In	dicate Nature of Notice, N	eport of Other D	aia	•	
NOTICE OF INTE	NTION TO:	SUBS	SEQUENT REF	PORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			K ALTERING CASING		
TEMPORARILY ABANDON 🔲 CI	RILY ABANDON 🔲 CHANGE PLANS 🗀 COMMENCE DE			P AND A	
PULL OR ALTER CASING 🔲 M	ULTIPLE COMPL	CASING/CEMENT	JOB 🗆 -		
DOWNHOLE COMMINGLE	:				
0711					
OTHER: 13. Describe proposed or completed	d amounting (Clearly state all s	OTHER:	aiva nantinant data	a including actions	X X
of starting any proposed work). proposed completion or recomp	SEE RULE 19.15.7.14 NMAC	C. For Multiple Con	ppletions: Attach w	ellbore diagram of	f .
PLUGBACK TO BONE SPRING					
3/19/13 – MIRU PU. ND wellhead. BU	BOP POOH with the				
3/21/13 – Tag CIBP @ 4500' and drill out. RIH with CIBP and set at 10,100'. Bail 35' cement on top of CIBP. Run GR/CBL/CCL					
9000' up to 8100'. Perforate squeeze holes @ 8550'.					
3/25/13 – Set treating pkr. @ 8500'. Establish injection rate into squeeze holes.					
3/26/13 – TIH with 5 1/2" cement retainer and set @ 8455'. Establish injection rate. Sting out/sting into retainer. Pressure up annulus					
To 500 psi. Mix and pump 300 sx Class H cement. WOC 48 hrs. 3/28/13 – Run GR/CBL/CCL. TOC @ 7420'. TIH drill cmt retainer & cement to 8750'. Pressure test csg.to 1500 psi – held ok.					
4/01/13 - Spot 2 bbls. 15% HCL-NE-FE					
4/02/13 – Acidize with 1500 gals. 15% H			Japi 6737-6746 (46	mores).	•
4/5/13 – Set CIBP @ 8500'. Spot 35' cement on top of plug.					
4/6/13 - Test 10K frac stack to 1000 psi					
4/8/13 – Perforate Bone Spring, 7583-77					
4/10/13 – Frac with 4463 bbls. Carrying				•	
4/17/13 – Run 237 jts. 2 7/8", 6.5#, N-80		and rods. Return to	production.		
4/30/13 – 24-hr. test: 2 BO, 20 MCF, 12			•		
		• •) \
I hereby certify that the information above	ve is true and complete to the bo	est of my knowledge	and belief.		₩ ^O
SIGNATURE Oldri MK	TITLE Agent		DATE	E_4/30/13	
Type or print name <u>Debbie McKelvey</u> For State Use Only	E-mail address: <u>debmc</u>	kelvey@earthlink.ne	et PHONE:5	75-392-3575	
£2) cd a	λ	P C		1 1 -	
APPROVED BY: ON (if any):	TITLE A So	11 Syperison	DA	ге 5/10/2013	· ·

