
Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103	
District I – (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011	
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		WELL API NO. 30-015-39933	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease	
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE STEE	
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			
PROPOSALS.)		RIVERSAND 36 STATE COM	
	Gas Well 🛛 Other	8. Well Number 1H	
2. Name of Operator	••	9. OGRID Number	
Devon Energy Production Company, LP 3. Address of Operator		10. Pool name or Wildcat	
3. Address of Operator 333 W. Sheridan Avenue, Oklahoma City, OK 73102		Eddy Undesignated; Wolfcamp (Gas)	
4. Well Location			
Unit Letter P: 660 feet from the South line and 660 feet from the East line			
Section 36		IMPM Eddy, County, NM	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
A CONTRACTOR OF THE SECOND	3068' GL		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN	TENTION TO		
NOTICE OF IN PERFORM REMEDIAL WORK □	PLUG AND ABANDON REMEDIAL WOR	SEQUENT REPORT OF: K □ ALTERING CASING □	
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRI		
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEMEN		
DOWNHOLE COMMINGLE	_	<u>—</u>	
OTHER:	□ OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
Plug and shandon 50' halo drilled by anyddon ria (Pytahas Dat Halo Carriaga)			
Plug and abandon 58' hole drilled by spudder rig (Butches Rat Hole Services)			
1. MIRU. TIH w/2-7/8" tubing and tag bottom.			
2. Spot cement from 58' to surface.			
3. Cut conductor 3' below ground level. Top out with cement & set dry hole marker. SEP 0 6 2013			
Approved for plugging of well hore only. NMOCD ARTESIA			
Lincolly under bond is not doned =	1	NMOCD ARTESIA	
which may be found at OCD Web Forms, www.cmnrd.state.nm.us/oc	4 11		
Spud Date:	Rig Release Date:		
-			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
Thereby beruity that the information of	above is true and complete to the best of my knowledge	c and ocher.	
SIGNATURE Rome Sta	1.	0/1/17	
SIGNATURE KMMe SIGNATURE	TITLE_Operations Technician_	DATE 9/4/ 13	
Type or print name Donnia Clast-	E mail addresse: Damia Clash @ 1	oom PHONE: 405 552 4615	
Type or print name _Ronnie Slack E-mail address: _Ronnie.Slack@dvn.com PHONE:405-552-4615 For State Use Only			
The same of the sa			
APPROVED BY: // WOO	CNL TITLE DIST OF SHOWIS	DATE 4 12/2013	
Conditions of Approval (if any):			

DEVON ENERGY PRODUCTION COMPANY LP			
Well Name: RIVERSAND 36 STATE COM 1H	Field: EDDY UNDESIGNATED; WOLFCAMP GAS		
Location: 660 FSL & 660' FEL; SEC 36-T22S-R27E	County: EDDY State: NM		
Elevation: 3068' GL	Spud Date: 2/28/12 Compl Date: Not completed		
API#: 30-015-39933 Prepared by: Ronnie Slack	Date: 8/29/13 Rev:		

PROPOSED PLUG & ABANDONMENT

48" Hole
30" conductor @ 10'
Cmt'd back to 3', fill dirt from 3' to surface

20" Open Hole from 10' to 58'



Proposed:

- 1. Cut conductor 3' BGL, top out w/cmt.
- 2. Set dry hole marker

Proposed:

1. Spot cmt from 58' to surface (Approx 90 sx cmt. 1.32 cu ft / sx

58' TD

