Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPRO	VED
OMB No. 1004-	0137
Everinger Index 2.1	201

BUREAU OF LAND MANAGEMENT	
RY NOTICES AND REPORTS ON WELLS	

5. Lease Serial No.

OCD Artesia

Do not use this t	IOTICES AND REPO form for proposals Use Form 3160-3 (A	to drill or to re-ei	nter an	6. If Indian, Allottee or	Tribe Name		
SUBMIT IN TRIPLICATE – Other instructions on page 2.			7. If Unit of CA/Agree East Shugart Unit	7. If Unit of CA/Agreement, Name and/or No.			
1. Type of Well Oil Well Gas V	Vell Other			8. Well Name and No. ESU # 38	•		
2. Name of Operator Americo Energy Resources, LLC				9. API Well No. 30-015-27429			
3a. Address		3b. Phone No. (include	e area code)	10. Field and Pool or E	•		
7575 San Filpie, Ste. 200 ,Houston, TX 77063		713-984-9700		Shugart: Yates- 7Rs-Queens- Grayburg			
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 1060' FSL & 2430' FEL of Sec. 34, T 18-S, R 31-E				1	11. Country or Parish, State Eddy County. New Mexico		
12. CHEC	CK THE APPROPRIATE BO	DX(ES) TO INDICATE	NATURE OF NO	OTICE, REPORT OR OTHE	ER DATA		
TYPE OF SUBMISSION	:	, , , , , , , , , , , , , , , , , , , ,	TYPE OF A	ACTION			
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat		Production (Start/Resume) Reclamation	Water Shut-Off Well Integrity		
Subsequent Report	Casing Repair	New Construc		Recomplete	Other		
Final Abandonment Notice	Change Plans Convert to Injection	☐ Plug and Aba.☐ Plug Back		Femporarily Abandon Water Disposal			
the proposal is to deepen direction Attach the Bond under which the violation of the involve testing has been completed. Final determined that the site is ready for 1- MIRU workover rig for parted rod 2- Pull out rods and pump. 3- Change the parted rod and check 4- Space out and put the well on pro-	vork will be performed or proved operations. If the operat Abandonment Notices must refinal inspection.) the pump.	ovide the Bond No. on f ion results in a multiple o	ile with BLM/BL completion or rec	 Required subsequent repompletion in a new interval, 	orts must be filed within 30 days a Form 3160-4 must be filed once		
20 3/17/2	014	MAR 1 4 20	114	SEE AT CONDI	TACHED FOR TIONS OF APPROVA		
14. I hereby certify that the foregoing is t Name (Printed/Typed) Mehdi Sadeghi	rue and correct.	Title I	Petroleum Engir	neer	•		
Signature Mehreli Sade	JADO	Date	01/06/2014	APP	SOMED		
	THIS SPACE	FOR FEDERAL	OR STATE (DEELCE IJSE			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

entitle the applicant to conduct operations thereon.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would

Approved by

CARLSBAD JELD OFFICE

East Shugart Unit 38 30-015-27429 Americo Energy Resources, LLC March 11, 2014 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by June 11, 2014.

- 1. Must conduct a casing integrity test to a minimum of 500 psi. Submit results to BLM. The CIT is to be performed on the production casing per Onshore Oil and Gas Order 2.III.B.1.h.
- 2. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Surface disturbance beyond the originally approved pad must have prior approval.
- 4. Closed loop system required.
- 5. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 6. Operator to have H2S monitoring equipment on location.
- 7. A minimum of a **2000** (**2M**) **BOP** to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 8. Subsequent sundry required detailing work done. Operator to include well bore schematic of current well condition when work is complete.

JAM 031114