Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
Office District I – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II - (575) 748-1283	OIL CONSERVATION DIVISION	30-015-00681
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa PC, INM 87505	6. State Oil & Gas Lease No.
87505		
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		
PROPOSALS.)		SOUTH RED LAKE II UNIT
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other		8. Well Number 27
2. Name of Operator		9. OGRID Number
LEGACY RESERVES OPERATING LP		240974
3. Address of Operator		10. Pool name or Wildcat
PO BOX 10848, MIDLAND, TX 79702		RED LAKE;QUEEN-GRAYBURG-SA
4. Well Location		
Unit Letter M : 990 feet from the SOUTH line and 330 feet from the WEST line		
Section <u>36</u> Township 17S Range 27E NMPM County EDDY		
	Elevation (Show whether DR, RKB, RT, GR, etc.)	
	3618' GR	
		· · · · · · · · · · · · · · · · · · ·
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
12. Check Appropriate Box to indicate Nature of Nonce, Report of Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A		
CLOSED-LOOP SYSTEM		
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
03/14/14 MIRU plugging equipment.		
03/17/14 Dug out cellar. ND wellhead. RIH w/ workstring and tagged plug @ 1200'. Circulated well with mud laden fluid.		
Spotted 25 sx cement @ 1200-953'. POH to 60'. ND BOP. Spotted 10 sx cement surface plug. Rigged down and moved off. 03/18/14 Moved in backhoe and welder. Cut off wellhead. Welded on "Above Ground Dry Hole Marker". Backfilled		
cellar. Removed deadmen. cleane		fround Dry Hole Warker . Dacknined
Install Closed-Loop System with steel tanks. Hauled contents from Closed-Loop System to approved NMOCD disposal		
location according to Rule 19.15.17.		
5	Approved for pluceting of a tri	-
	the state of the second s	
	which may be found at OCD Web Page under Forms, www.cmnrd.state.pm.usford.	RECEIVED
Spud Date:	Rig Release Date:	1 / · · A 2011
· · · · · · · · · · · · · · · · · · ·		· · ·
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
NONLITER LAS in Harris		
SIGNATURE NEW Drow	TITLE_OPERATIONS SUPERI	NTENDENTDATE03/19/2014
Type or print name KEVIN BRACE	- V E mail address:	DUONE. 422 (90 5200
	Y E-mail address:	PHONE: _432-689-5200
For State Use Only		
APPROVED BY:	TITLE STATE	DATE 365-2014
Conditions of Approval (if any):		
$\frac{1}{2} \int \frac{1}{2} \int \frac{1}$		

- -

* Submit Subsequent C-103