

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised August 1, 2011

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-005-62887
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-5961 & VB-0402
7. Lease Name or Unit Agreement Name Conestoga State
8. Well Number 1
9. OGRID Number 001092
10. Pool name or Wildcat Palma Mesa

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator
Armstrong Energy Corporation

3. Address of Operator
P.O. Box 1973, Roswell, NM 88202-1973

4. Well Location
 Unit Letter P : 330 feet from the South line and 990 feet from the East line
 Section 14 Township 8S Range 27E NMPM Chaves County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK PLUG AND ABANDON
 TEMPORARILY ABANDON CHANGE PLANS
 PULL OR ALTER CASING MULTIPLE COMPL
 DOWNHOLE COMMINGLE

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ALTERING CASING
 COMMENCE DRILLING OPNS. P AND A
 CASING/CEMENT JOB

OTHER:

OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 03-24-14 MIRU, ND wellhead, install BOP. RIH w/ tbg, circ hole w/ Brine mud, spot 25 sx Class "C" cement @ 4956', POH. SDON
- 03-25-14 Work csg, cut 5-1/2" csg @ 3275', POH and lay down 75 jts and 2 cut offs. SDON
- 03-26-14 RIH w/ tbg to 3335', spot 50 sx Class "C" cement w/ 2% CaCl2, POH, WOC. RIH, tag @ 3242', 93' plug, spot 30 sx @ 3242'. POH. SDON
- 03-27-14 RIH, tag @ 3225', 110' total plug. POH to 2751', spot 75 sx plug, POH, WOC. RIH, tag @ 2605', 152' plug, POH to 592', spot 50 sx plug, POH, WOC. SDON
- 03-28-14 RIH, tag @ 543', 49' plug, pumped 50 sx @ 543', POH, WOC. RIH, tag @ 332', 260' plug total. POH to 60', pump 20 sx and fill to Surface. ND, cut off wellhead, install Dry Hole plate, back-fill cellar, cut off anchors, clean location. RD, move equipment off.

Will notify OCD when location is rehabilitated and re-seeded.

Approved for plugging of well bore only.
 Liability under bond is retained pending receipt of C.O.D. (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms. www.emnrd.state.nm.us/oed.

RECEIVED
 APR 18 2014
 NMOCD ARTESIA

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bruce Stubbs TITLE Vice President - Operations DATE 04/17/14

Type or print name Bruce Stubbs E-mail address: bastubbs@armstrongenergycorp.com PHONE: 575-625-2222

For State Use Only

APPROVED BY: AP Dade TITLE Dist. Supervisor DATE 5/12/2014

Conditions of Approval (if any) * Subsequent C-103 needs to be Submitted