

## UNITED STATES OCD A DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD	Artesia
$\cap$ P	

	OMB No. 1004-0137
	Expires: July 31, 2010

FORM APPROVED

5. Lease Serial No. NMNM 028500

6. If Indian, Allottee or Tribe Name

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

abanaonea wen.		B) for such propose		<u> </u>		
	T IN TRIPLICATE – Other	instructions on page 2.	, .	7. If Unit of CA/Agree	ment, Name and/or No	).
1. Type of Well  ✓ Oil Well Gas W	ell Other			8. Well Name and No. Hill Federal 1 & 2	25	 5082
2. Name of Operator Ray Westall Operating, Inc.	·			9. API Well No. See attached	2-015-25	1862
3a. Address P.O. Box 4 Loco Hills, NM 88255		3b. Phone No. <i>(include area c</i> ) 575-677-2370	ode)	10. Field and Pool or E Hackberry; Yates - 7	xploratory Area	
4. Location of Well (Footage, Sec., T., Several	R.,M., or Survey Description	)		11. Country or Parish, Eddy County, NM	State	
12. CHEC	K THE APPROPRIATE BO	X(ES) TO INDICATE NATU	RE OF NOTIC	E, REPORT OR OTHE	R DATA	
TYPE OF SUBMISSION		Т	YPE OF ACT	ION		
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	=	uction (Start/Resume) amation	Water Shut-Off Well Integrity	
Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abandon		mplete oorarily Abandon	OtherOPERATO	· · · · · · · · · · · · · · · · · · ·
Final Abandonment Notice	Convert to Injection	Plug Back	Wate:	r Disposal	CHANGE	
Attach the Bond under which the w following completion of the involve testing has been completed. Final determined that the site is ready for Operator has changed from Endural Ray Westall Operating, Inc., as new lease or portion of lease described. Ray Westall Operating, Inc. meets for Bond Coverage: Statewide BLM Bond NMXXXXXX  Effective date of the change is April Accepted for record NMACCD.	ed operations. If the operation Abandonment Notices must final inspection.)  Ince Resources, LLC to Rational operator, accepts all apprehensional bonding requirements and the subject of	on results in a multiple complete be filed only after all requirementary Westall Operating, Inc. licable terms, conditions, stipunts as follows:	ion or recompl nts, including oulations and	letion in a new interval, reclamation, have been restrictions concerning	a Form 3160-4 must be completed and the open ground	pe filed once erator has
<ul><li>14. I hereby certify that the foregoing is to Name (Printed/Typed)</li><li>Ray Westall</li></ul>	ue and correct.	Title 1	) 500/c/(-	eeper		·
Signature Lev H	ope:	. Date . 04/15/2				
	THIS SPACE	FOR FEDERAL OR S	TATE OFF	ACP PSENVF	D	
Conditions of approval, if any are attached that the applicant holds legal or equitable to entitle the applicant to conduct operations.  Title 18 U.S.C. Section 1001 and Title 43 fictitious or fraudulent statements or repre	itle to those rights in the subject thereon.	ct lease which would Office	and willf BlyRe	MAY 1 6 2014		d States any false,
ricutious of traudulent statements of repre	sentations as to any matter wit	inin its jurisdiction.	1 (	CHULODAD LIFTO OF	1106	•

Well Name	ULSTR	API Number	Footage		Pool
Hill Federal 1	H-21-T19S-R31E	30-015-24863	1980' FNL & 660' FEL	29490	Hackberry Yates 7 Rivers, North
Hill Federal 2	A-21-T19S-R31E	30-015-25082	990' FNL & 660' FEL	29490	Hackberry Yates 7 Rivers, North

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Effective 4/1/2014 Bond NM0322

## 5/16/2014 Approved subject to Conditions of Approval. JDB Change of Operator Conditions of Approval

- 1. Tank battery must be bermed/diked (must be able to contain 1 1/2 times the volume of the largest tank).
- 2. Submit for approval of water disposal method.
- 3. Submit updated facility diagrams as per Onshore Order #3
- 4. This agency shall be notified of any spill or discharge as required by NTL-3A.
- 5. All outstanding environmental issue must be addressed within 90 days. Contact Jim Amos for inspection and to resolve environmental issues. 575-234-5909
- 6. Install legible well sign on location with operator name, well name and number, lease number, unit number, 1/4 1/4, section, township, and range. NMOCD requires the API number on well signs.
- 7. Subject to like approval by NMOCD.
- 8. All Reporting to ONRR (OGOR Reports) must be brought current within 30 days of this approval including any past history.
- 9. If this well is incapable of producing in paying quantities submit NOI to plug and abandon this well or obtain approval to do otherwise within 90 days.
- 10. If not in place acquire operating rights on this lease within 30 days with BLM office in Santa Fe, NM.