Submit l Copy To Appropriate District Office 4	State of New	Mexico		Form C-103	
<u>District I</u> – (575) 393-6161	Energy, Minerals and I	Natural Resources	WELL API NO.	Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OH COMCEDIATI	ON DIVIGION	30-015-20202		
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410	i., Aztec, NM 87410 Sonto Eq. NIM 97505		STATE FEE S 6. State Oil & Gas Lease No.		
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa 1 c, 1viv	11 97303	6. State Off & Ga	is Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name Mitchell IN		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			8. Well Number		
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator			9 OGRID Numb	9. OGRID Number	
Yates Petroleum Corporation			025575	025575	
3. Address of Operator			10. Pool name or Wildcat		
105 South Fourth Street, Artesia, N	√M 88210 ————————————————————————————————————		Eagle Creek; San	Andres	
4. Well Location Unit Letter J :	2310 feet from the S	South line and	2310 feet from	the East line	
Section 23	Township 17S	Range 25E	NMPM Edd	y County	
"我们"于约定为 了	11. Elevation (Show whether		:.)		
PRODUCT THEORY TO SEE THE SECOND SECO	3	495'GR		The state of the s	
12. Check A	Appropriate Box to Indicat	te Nature of Notice	, Report or Other	Data	
NOTICE OF IN	ITENTION TO:	SUE	- BSEQUENT RE	PORT OF:	
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WO				ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS		RILLING OPNS.	P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	NT JOB 📙		
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM					
OTHER:		OTHER:			
13. Describe proposed or comp					
proposed completion or rec	ork). SEE RULE 19.15.7.14 NI completion.	MAC. For Muniple Co	ompietions: Attach v	vendore diagram of	
	•				
Yates Petroleum Corporation plans	to plug and abandon this well as	s follows:			
1. NU BOP. TOH with production	equipment.				
2. Make a scraper run to 1350' then	spot a 50 sx Class "C" cement				
at surface. For casing strings without 3. Tag top of cement plug at 1060'.			culate cement to surf	ace as necessary.	
4. Cut off wellhead, install marker		III 30 SX.			
Wellbore schematics attached		Approved for plugging of		NM OIL CONSERVATION	
onoore senematics attached	•	Liability under bond is re of C-103 (Subsequent Re		ARTESIA DISTRICT	
CONDITIONS OF APPROVAL ATTAC	CHED	which may be found at O Forms, www.cmnrd.state.	.,	OCT 27 2014	
A Complete description was	who in	Forms, www.cmiird.state.	nm.us/ocd.		
Approval Granted providing wo	Rig Releas	se Date:		RECEIVED	
Completed by 10/28/2015				, (COLL)	
I hereby certify that the information	above is true and complete to the	he best of my knowled	ge and belief.		
	Λ_{-}				
SIGNATURE (Charles	TITLE _	Regulatory Reporting	Supervisor DATE	October 23, 2014	
Type or print name Tina Hud	erta E-mail address:	tinah@yatespetroleu	ım.com PHON	E: <u>575-748-4168</u>	
For State Use Only	_// ~			, ,	
APPROVED BY:	\mathcal{O} L TITLE \mathcal{D}	IST HOLDEN	J/SP DA	TE 10/28 /2014	
Conditions of Approval (if any):	de TITLED Hacked COA'S				
A 500 A	Herhod COHS				
p Jec /1	(100 et. 30),				


Well Name: Mitchell IN #1 Field: Eagle Creek Location: 2310' FSL & 2310' FEL Sec 23-17S-25E


County: Eddy State: New Mexico GL: 3,495' Zero: KB:

Spud Date: 1/28/1969 Completion Date: 3/25/1969

Comments: API # 30-015-20202

BEFORE





 $4\,\%$ " & 5 % " csg @ 1,505' cmtd w/ 100 sx.

TD 1,505'

DATE: 9/8/2014

Well Name: Mitchell IN #1 Field: Eagle Creek
Location: 2310' FSL & 2310' FEL Sec 23-17S-25E


County: Eddy State: New Mexico
GL: 3,495' Zero: KB:

Spud Date: 1/28/1969 Completion Date: 3/25/1969

Comments: API # 30-015-20202

AFTER

Casing Program				
Size/Wt/Grade	Depth Set			
10 ¾" 30# K-55	92'			
7" 20# K-55	1,169'			
4 ½" 11# & 5 ½" 15.5# K-55	1,505'			



50 sx cmt plug @ 300'-surface

10 3/4" csg @ 92' cmtd w/ 25 sx.

7" csg @ 1,169' cmtd w/ 1025 sx.

6 1/4" hole

50 sx cmt plug @ 1,350'-1,060'

San Andres perfs 1,366'-1,416' (25)

4 ½" & 5 ½" csg @ 1,505' cmtd w/ 100 sx.

TD 1,505'

DATE: 9/8/2014

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: Yates Petro Jeum Corp.	
Well Name & Number: Mitchell IN #1	
API#: 30-015-20202	

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 1 year of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.

11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 10/28/2014

APPROVED BY: SO

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - Any Salt Section (Plug at top and bottom)
 - o Aba
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing
 must be cut and pulled with plugs set at these depths or casing must be perforated and cement
 squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).