•			CONSERV	/ATIO	N			
Form 3160-5 (April 2004) ARTESTA DISTRICT DEPARTMENT OF THE INTERIORMAR () 2 2005 BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an					FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 5. Lease Serial No.			
					NMNM33437         6.         If Indian, Allottee or Tribe Name			
abandoned w	vell. Use Form 3160-3	(APD) for such	re-enter an proposals.			I, Anouce of The Name		
SUBMIT IN TRIPLICATE- Other instructions on reverse side.         1. Type of Well       Gas Well         Oil Well       Gas Well         Other       Other         2. Name of Operator       NADEL AND GUSSMAN HEYCO, LLC						<ul> <li>7. If Unit or CA/Agreement, Name and/or No.</li> <li>PMS 8 Federal</li> <li>8. Well Name and No.</li> </ul>		
					8. Well Na			
					<b>PMS 8</b> 9. API W	Federal #3 ell No.		
3a         Address         3b.         Pho           PO BOX 1936 ~ ROSWELL NM 88202-1936         575.6			clude area code)		3001526127 10. Field and Pool, or Exploratory Area			
Location of Well (Footage, Sec.,				Shugart; Bone Spring North				
1980' FNL & 660' FWL, Sec. 8 NWNW, T18S, R31E					11. County or Parish, State Eddy, New Mexico			
12. CHECK A	PPROPRIATE BOX(ES) TO	DINDICATE NA	TURE OF NO	)TICE,		R OTHER DATA		
TYPE OF SUBMISSION TYPE OF ACTION								
Notice of Intent	Acidize Alter Casing Casing Repair Change Plans	Deepen Fracture Treat New Construct Plug and Abana		luction (S lamation omplete	Start/Resume) Water Shut-Off Well Integrity Other Change of Operator			
Final Abandonment Notice	Convert to Injection	Plug Back		er Dispos	al			
Attach the Bond under which following completion of the ir testing has been completed. F determined that the site is read This is a notification of C Harvey E. Yates Compar	ectionally or recomplete horizonta the work will be performed or pro- ivolved operations. If the operation inal Abandonment Notices shall be by for final inspection.) hange of Operator on the abo- ty, as new operator, accept all r portion of lease described.	vide the Bond No. on n results in a multiple e filed only after all re we referenced well.	file with BLM/B completion or rec quirements, inclu	BIA. Requ completion iding recla	uired subsequent n in a new intervantation, have be	reports shall be filed within a al, a Form 3160-4 shall be fil en completed, and the operat	30 days led once or has	
BLM Bond No. NMB000 Harvey E. Yates Compar								
P.O. Box 1933 Roswell, NM 88202-1933	SEE ATTACHED FOR							
•					ONDITIONS OF APPROVAL			
	Ac C AD	NHIOCD	cord 3/2/15					
14. I hereby certify that the for Name (Printed/Typed)	egoing is true and correct	· I			Appr	ROVED	]	
Tammy R. Linl		Tit	e Production	Tech				
Signature an	y K. Link	Da	te		09/10/2014	2 3 2015	2	
L	THIS SPACE FOR	FEDERAL O	R STATE C	FFIC	EUSE	- Kancho	32	
Approved by			Title	PO	REAU OF LA	ND MANAGEMENT	$\left[ \right]$	
Conditions of approval, if any, are certify that the applicant holds leg which would entitle the applicant	al or equitable title to those rights		Office <sup>i</sup>				1	
Title 18 U.S.C. Section 1001 and Tit States any false, fictitious or fraudu	le 43 U.S.C. Section 1212, make it	a crime for any pers	on knowingly an	nd willfull	y to make to an	y department or agency of	the United	

(Instructions on page 2)

A

£

## BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE 620 E. Greene St Carlsbad, NM 88220 Ph: (575) 234-5972

## **Conditions of Approval for Change of Operator**

- 1. Tank battery must be bermed/diked (must be able to contain 1 1/2 times the volume of the largest tank).
- 2. Submit for approval of water disposal method.
- 3. Submit updated facility diagrams as per Onshore Order #3
- 4. This agency shall be notified of any spill or discharge as required by NTL-3A.
- 5. All outstanding environmental issue must be addressed within 90 days. Contact Jim Amos for inspection and to resolve environmental issues. 575-234-5909
- 6. Install legible well sign on location with operator name, well name and number, lease number, unit number, 1/4 1/4, section, township, and range. NMOCD requires the API number on well signs.
- 7. Subject to like approval by NMOCD.

: 12

- 8. All Reporting to ONRR (OGOR Reports) must be brought current within 30 days of this approval including any past history.
- 9. If this well is incapable of producing in paying quantities submit NOI to plug and abandon this well or obtain approval to do otherwise within 90 days.
- 10. Submit plan for approval of well operations for all TA/SI wells within 30 days of this approval to change operator.
- 11. If not in place acquire operating rights on this lease within 30 days with BLM office in Santa Fe, NM.

5 62

14

1.12