Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NA OUCCONSERVATION ARTESIA DISTRICT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS FAR 0 2 2015

5. Lease Serial No. NMLC061705A

abandoned we	6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No. 891000303E	
Type of Well	8. Well Name and No. POKER LAKE UNIT 078				
2. Name of Operator Contact: TRACIE J CHERRY BOPCO LP E-Mail: tjcherry@basspet.com				9. API Well No. 30-015-27536	
3a. Address P O BOX 2760 MIDLAND, TX 79702		3b. Phone No. (include area code) Ph: 432-221-7379		10. Field and Pool, or Exploratory POKER LAKE; DELAWARE SW	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, and State	
Sec 25 T24S R30E NENE 666	EDDY COUNTY, NM				
·					
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, RI	EPORT, OR OTHE	R DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
☐ Notice of Intent ☑ Subsequent Report ☐ Final Abandonment Notice	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)		☐ Water Shut-Off
	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation		■ Well Integrity
	□ Casing Repair	■ New Construction	☐ Recomplete		☑ Other Venting and/or Flari ng
	Change Plans	Plug and Abandon	□ Temporarily Abandon□ Water Disposal		
	☐ Convert to Injection	Plug Back			
13. Describe Proposed or Completed Op If the proposal is to deepen directions Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al	ally or recomplete horizontally, rk will be performed or provide I operations. If the operation res	give subsurface locations and meas the Bond No. on file with BLM/BL sults in a multiple completion or rec	ured and true ve A. Required sul ompletion in a r	ertical depths of all perting sequent reports shall be new interval, a Form 316	nent markers and zones. filed within 30 days 10-4 shall be filed once

determined that the site is ready for final inspection.)

BOPCO, LP respectfully submits this sundry notice to report the volume flared for 90-days on the referenced agreement. Wells contributing to the flaring volume are as follows:

Lease number/well/API

NMLC061705B / POKER LAKE UNIT 100 / 30-015-27961-00-S1 NMLC061705B / POKER LAKE UNIT 103 / 30-015-27919-00-S1 State - E2206 / POKER LAKE UNIT 105 / 30-015-27895-00-S1 NMLC061705B / POKER LAKE UNIT 106 / 30-015-27920-00-S1 NMNM0157779 / POKER LAKE UNIT 108 / 30-015-28086-00-S1 NMNM0157779 / POKER LAKE UNIT 111 / 30-015-28087-00-S1 State - B10685 / POKER LAKE UNIT 114 / 30-015-28102-00-S1

14. I hereby certify that t	he foregoing is true and correct. Electronic Submission #222915 verifie For BOPCO LP, so Committed to AFMSS for processing	nt to th	the Carlsbad			
Name (Printed/Typed)	TRACIE J CHERRY	Title	REGULATORY ANALYST			
Signature	(Electronic Submission)	Date	ACCEPTED FOR RECORD			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved By		Title	// FEB 2/0 2015/			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	BUREAU OF LAND MANAGEMENT CARYSBAD FIELD OFFICE			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and villfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #222915 that would not fit on the form

32. Additional remarks, continued

STATE - B10685 / POKER LAKE UNIT 115 / 30-015-28180-00-S1 NMLC061705A / POKER LAKE UNIT 118 / 30-015-29213-00-S1 NMLC061705A / POKER LAKE UNIT 78 / 30-015-27536-00-S1 NMLC061705A / POKER LAKE UNIT 80 / 30-015-27537-00-S1 NMNM030453 / POKER LAKE UNIT 82 30-015-27752-00-S1 NMNM0506A / POKER LAKE UNIT 83 / 30-015-27753-00-S1 STATE NMB10685 / POKER LAKE UNIT 84 / 30-015-29103-00-S1 NMLC061705B / POKER LAKE UNIT 85 / 30-015-27911-00-S1 NMLC061705B / POKER LAKE UNIT 86 / 30-015-27912-00-S1 NMLC061705B / POKER LAKE UNIT 87 / 30-015-27986-00-S1 NMLC061705B / POKER LAKE UNIT 89 / 30-015-27787-00-S1 NMNM030453 / POKER LAKE UNIT 92 / 30-015-27797-00-S1 NMNM030453 / POKER LAKE UNIT 93 / 30-015-27798-00-S1 NMNM030453 / POKER LAKE UNIT 93 / 30-015-32823-00-S1

Intermittent flaring was necessary due to restricted pipeline capacity at respective sales points.

4134 MCF was flared for the period Sept-Nov 2012

: 40