

Submit One Copy To Appropriate District Office  
 District I 1625 N. French Dr., Hobbs, NM 88240  
 District II 811 S. First St., Grand Ave., Artesia, NM 88210  
 District III 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

State of New Mexico

Energy, Minerals and Natural Resources

Form C-103

Revised August 1, 2011

JUL 23 2015

**OIL CONSERVATION DIVISION**

**RECEIVED** 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

WELL API NO.	30-015-10442
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	E-4397
7. Lease Name or Unit Agreement Name	Bass
8. Well Number	003 SWD
9. OGRID Number	260737
10. Pool name or Wildcat	E. Willman Queen Grayburg

**SUNDRY NOTICES AND REPORTS ON WELLS**  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  Oil Well  Gas Well  Other

2. Name of Operator: BOPCO, L.P.

3. Address of Operator: P.O. Box 2760 Midland, TX 79702

4. Well Location  
 Unit Letter F : 2310 feet from the North line and 1650 feet from the West line  
 Section 12 Township 19S Range 28E NMPM County Eddy

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	P AND A <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>
MULTIPLE COMPL <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	<input checked="" type="checkbox"/> Location is ready for OCD inspection after P&A

- All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
- Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
- A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

**OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.**

- The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
- Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
- If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
- All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
- All other environmental concerns have been addressed as per OCD rules.
- Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE Tracie J Cherry TITLE Sr Regulatory Analyst DATE 07/20/2015

TYPE OR PRINT NAME Tracie J Cherry E-MAIL: tjcherry@basspet.com PHONE: (432)683-2277

APPROVED BY: [Signature] TITLE Compliance Officer DATE 8/12/15

Conditions of Approval (if any): OK - to be Released