Form 3160-5 (August 2007)

	FORM.	APPR	OVEI	j
	OMB N	O. 100	04-013	5
	Expires:	July 3	1, 201	l
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			-	•

10.10	
5.	Lease Scrial No.
	NMNM103878


		HOme.	esia				
Form 3160-5 (August 2007) DE	UNITED STATUS OIL CO EPARTMENT OF THE INTERPORE UREAU OF LAND MANAGEMENT	FO OM Expi	FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lense Scrial No.				
SUNDRY NOTICES AND REPORTS ON WELLS			5. Lease Scrial No NMNM1038				
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such promy நூ			6. If Indian, Allot	6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRI	PLICATE - Other instructions on r	everse side.	7. If Unit or CA/A	Agreement, Name and/or No.			
1. Type of Well Gas Well Other			8. Well Name and RUSSELL 8 F				
Name of Operator Contact: ERIN WORKMAN DEVON ENERGY PRODUCTION CO EMail: ERIN.WORKMAN@DVN.COM			9. API Well No. 30-015-31392-00-S1				
3a. Address 333 WEST SHERIDAN AVE OKLAHOMA CITY, OK 73102 3b. Phone No. Ph: 405-55		No. (include area code) 552-7970	10. Field and Pool, or Exploratory BURTON FLAT				
4. Location of Well (Footage, Sec., T		11. County or Par	ish, and State				
Sec 8 T20S R29E NWNW 760FNL 660FWL			EDDY COUNTY, NM				
12. CHECK APPI	ROPRIATE BOX(ES) TO INDICA	TE NATURE OF N	OTICE, REPORT, OR OT	HER DATA			
TYPE OF SUBMISSION		TYPE OF	ACTION				
Notice of Intent ■		eepen	☐ Production (Start/Resume				
Description □ Subsequent Report		racture Treat ew Construction	☐ Reclamation Recomplete	☐ Well Integrity ☐ Other			
☐ Final Abandonment Notice		lug and Abandon	☐ Temporarily Abandon	U Omer			
1 mai / toundomment / touce	- , *	lug Back	☐ Water Disposal				
following completion of the involved testing has been completed. Final Ab determined that the site is ready for final Devon Energy Production Corcoa that were attached to the 1) In regards to plugging back insure we had enough room to our frac grows down into the 3 9250-9264? Is it acceptable to a time in the future when the way. 2) In regards to testing the 5-1 cement behind pipe from 5614	npany, LP respectfully requests the fapproval on 07/01/15 for the Russe the Wolfcamp, I purposely did not pur run a tracer survey post 3rd BSS from the BSS ?H sands? (see attached log o not set a plug over this zone at this yell needs to be plugged and abandowle with the work of th	iple completion or recordil requirements, including adjustments of the second of the second of the second of the second of the casing does of the casing does of the casing and a pack of the second o	Information System In greclamation, have been completed by the plan TIONS OF the Carlshad	3160-4 shall be filed once ed, and the operator has 20 7/30/5 Copied for record NMOCD			
Name(Printed/Typed) ERIN WOR		ł .	TORY COMPLIANCE REO				
Signature (Electronic S		Date 07/09/20					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By	Title	1 Maganoth	WALLE Date				
Conditions of approval, if any, are attached ertify that the applicant holds legal or equivalent would entitle the applicant to conduction.	Office	BURYARI SBAD FILE					
Fitle 18 U.S.C. Section 1001 and Title 43 U.S. States any false, fictitious or fraudulent s	J.S.C. Section 1212, make it a crime for any latements or representations as to any matter	person knowingly and wwithin its jurisdiction.	villfully to make to any department	t or agency of the United			

Additional data for EC transaction #308654 that would not fit on the form

32. Additional remarks, continued

is to isolate each interval and test the tubing and casing that will be exposed to frac treating pressures before perforating and fracking (I will test the tubing casing annulus to 1000 psi to insure casing integrity and will monitor said annulus during the stimulation for communication, shutting the job down in the case of communication). Is this acceptable?

Thank You for your time and consideration!



Russell 8 Federal 1 30-015-31392 Devon Energy Production Co., LP July 20, 2015 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by October 20, 2015.

- 1. Operator shall place CIBP at 10,762' (minimum 50' above top most perf) and place 25sx of Class H cement on top as proposed. WOC and tag.
- 2. Operator must plug back the Wolfcamp formation properly when abandoning the Bone Spring formation.
- 3. A CIT is to be performed on the production casing per Onshore Oil and Gas Order 2.III.B.1.h.
- **4.** Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 5. Surface disturbance beyond the originally approved pad must have prior approval.
- 6. Closed loop system required.
- 7. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 8. Operator to have H2S monitoring equipment on location.
- 9. A minimum of a **3000** (**3M**) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.

10. Subsequent sundry required detailing work done and completion report with the new formation. Operator to include well bore schematic of current well condition when work is complete.

11. See attached for general requirements.

JAM 072015

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-393-3612
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat** Class "C", for up to 7,500 feet of depth or **Neat** Class "H", for deeper than 7,500 feet plugs.

6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u>

7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.