

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-22799
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Jackson AT
1. Type of Well: Oil Well ☐ Gas Well ☒ Other	8. Well Number 9	9. OGRID Number 025575
2. Name of Operator Yates Petroleum Corporation	10. Pool name or Wildcat Eagle Creek Atoka Morrow	
3. Address of Operator 105 S. 4 th Street, Artesia, NM 88210		
4. Well Location Unit Letter M : 660 feet from the South line and 660 feet from the West line Section 13 Township 17S Range 25E NMPM Eddy County	11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3465'GR	
Pit or Below-grade Tank Application ☐ or Closure ☐		
Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____		
Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: Fishing operations ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

12/5/05 - 1/9/06

Latch onto tubing to unset packer. Tubing was parted at 1800'. POH with 1800' of tubing. Tubing was jagged at the end it was parted. Could not grab hold of tubing. Try to fish tubing. Tagged 5' high of fish. No fish recovered. Started washing over fish. Had several pieces of tubing and possible casing. Was getting some formation back in returns and started getting some scale back before shoe quit. TIH with new shoe. Washed down over 29' of fish. POOH with shoe. Did not have any junk in shoe. Cut 9" of new hole. Shoe plugged off. POOH with shoe. Had several PCS of junk tubing and shale. TIH with new shoe. Washed over all but 10' of fish. Circulated clean. Made 110' of new hole. POOH with shoe. Lack 60' of getting to 2232'. POOH with cutter. TIH with new shoe. Tagged at 2085'. Worked over fish. Washed down to 2131' and quit. POOH with shoe - had a bunch of junk metal wadded up in shoe. TIH with new shoe. Tagged at 2085'. Washed down over fish to 2137'. Did not recover any junk. Latch onto fish with overshot at 2090'. Milled off 10' of fish. Could not get past 2090'. TIH with shoe and washpipe. Washed down past 2090' and cut 11' with shoe. Circulate hole clean and prep to pull shoe. Washed down to 2101'. Cut over fish down to 2128'. Circulated hole clean. Shoe quit cutting. Made 17'. Top of fish at 2090'. Went down to 2128' - could not cut. TIH with new shoe. Tagged at 2128' and cut 4' down to 2132'. Circulated clean. TIH with new shoe. Cut down to 2136'. Made 4'. Shoe wore out. TIH with new shoe. Cut down to 2140'. Circulated clean and POOH with shoe. Tagged fish at 2140'. Cut 3'. Circulated clean. POOH with shoe. Set a cement retainer at 1151'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Tina Huerta TITLE Regulatory Compliance Supervisor DATE January 17, 2005

Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471

For State Use Only

APPROVED BY: _____ DATE _____
Conditions of Approval (if any): Accepted for record - NMOCD