UNITED STATES NM OIL CONSERVATION
DEPARTMENT OF THE INTERIORARTESIA DISTRICT
BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELL'S 0 2015D Arcesia

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for any analysis.

5. Lease Serial No. NMNM81586

abandoned we	o. If findian, Afforce C	o. If findian, Another of Title Name			
SUBMIT IN TRI	7. If Unit or CA/Agre	7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well  ☑ Oil Well ☐ Gas Well ☐ Oth		8. Well Name and No. CEDAR CANYON 23 FEDERAL 4H			
Name of Operator     OXY USA INCORPORATED     Contact: DAVID STEWART     E-Mail: david_stewart@oxy.com			9. API Well No. 30-015-43281-00-X1		
3a. Address       3b. Phone N         5 GREENWAY PLAZA STE 110       Ph: 432.6         HOUSTON, TX 77046-0521		Phone No. (include area code 432.685.5717	10. Field and Pool, or PIERCE CROS	10. Field and Pool, or Exploratory PIERCE CROSSING	
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)		11. County or Parish,	11. County or Parish, and State	
Sec 22 T24S R29E SENE 14	15FNL 155FEL		EDDY COUNTY	/, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO INI	DICATE NATURE OF	NOTICE, REPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent     ■	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	■ Water Shut-Off	
_	☐ Alter Casing	☐ Fracture Treat	□ Reclamation	■ Well Integrity	
☐ Subsequent Report	□ Casing Repair		☐ Recomplete	Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	□ Temporarily Abandon	Change to Original A PD	
	Convert to Injection	□ Plug Back	☐ Water Disposal		
following completion of the involved	operations. If the operation results in pandonment Notices shall be filed onlined in in all inspection.)  quests approval for the following	n a multiple completion or rec y after all requirements, including g changes to the approv	th skidding SEE ATTACHED EC	0-4 shall be filed once and the operator has	
Batch drilling operations:  1. Drill surface hole on first we 2. Skid back to the first nipple 3. Skid to second well and nip 4. Skid to first well and nipple	up and test BOPE and drill int ple up and test BOPE and dril up and test BOPE and drill pro	Intermediate and production hole	CUNDITIONS OF AI	PPROVAL	
14. I hereby certify that the foregoing is	true and correct.		/		
Commit	Electronic Submission #32386 For OXY USA INC tted to AFMSS for processing b	ORPORATED, sent to the	Carlsbad		
Name (Printed/Typed) DAVID STEWART		Title REGUL	Title REGULATORY ADVISOR		
Signature (Electronic S	Submission)	Date 11/18/2	APPRO	VED	
•	THIS SPACE FOR F	EDERAL OR STATE	OFFICE USE		
Approved By		Title	NOV 23	2015 Date	
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to condu	itable title to those rights in the subje		BUREAU OF LAND M CARLSBAD FIEL	ANAGEMENT	



Walls, Christopher <cwalls@blm.gov>

# FW: Sundries for Cedar Canyon 23 Federal 5H & 4H

Chan\_Tysor@oxy.com < Chan\_Tysor@oxy.com>

Mon, Nov 23, 2015 at 1:39 PM

To: cwalls@blm.gov

Cc: tkrueng@blm.gov, Diego\_Tellez@oxy.com, David\_Stewart@oxy.com

Chris,

Apologies for missing the attachment.

We will use a blind cap to prevent anything from falling into the well and between skids to secure it.

Please see attached.

Thanks,

## R. Chan Tysor

Drilling Engineer - Oxy Permian Primary

Office: 713-513-6668

Cell: 832-564-6454

Chan\_Tysor@Oxy.com


From: Walls, Christopher [mailto:cwalls@blm.gov]

**Sent:** Monday, November 23, 2015 2:36 PM **To:** Tysor, Chan < Chan\_Tysor@Oxy.com>


Cc: Teungku Muchlis Krueng <tkrueng@blm.gov>; Tellez, Diego <Diego\_Tellez@oxy.com>

Subject: Re: FW: Sundries for Cedar Canyon 23 Federal 5H & 4H

[Quoted text hidden]



Note: Dimensional information reflected on this drawing are estimated measurements only.





11 5KMBSw/5.5 Mandrel

Turnkey Spud Rig
•SENM

•Jeanett

•6-29-15

Worldn

**CAMERON** 

.e: •# •J-9579-

## PECOS DISTRICT CONDITIONS OF APPROVAL

OPERATOR'S NAME:

OXY USA Inc

LEASE NO.: | NM81586

WELL NAME & NO.: |

Cedar Canyon 23 Fed Com 4H

SURFACE HOLÉ FOOTAGE:

1352'/N & 195'/E Sec. 22

BOTTOM HOLE FOOTAGE

1415'/N & 2460'/E Sec. 24

LOCATION:

Section 24, T. 24 S., R. 29 E., NMPM

COUNTY:

Eddy County, New Mexico

The operator has proposed to drill multiple wells utilizing a skid/walking rig. Operator shall secure the wellbore on the current well as proposed after installing and testing the wellhead, by installing a blind flange of like pressure rating to the wellhead and a pressure gauge that can be monitored while drilling is performed on the other well.

### A. CASING

Changes to the approved APD casing program need prior approval if the items substituted are of lesser grade or different casing size or are Non-API. The Operator can exchange the components of the proposal with that of superior strength (i.e. changing from J-55 to N-80, or from 36# to 40#). Changes to the approved cement program need prior approval if the altered cement plan has less volume or strength or if the changes are substantial (i.e. Multistage tool, ECP, etc.). The initial wellhead installed on the well will remain on the well with spools used as needed.

Centralizers required on surface casing per Onshore Order 2.III.B.1.f.

## Wait on cement (WOC) for Water Basin:

After cementing but before commencing any tests, the casing string shall stand cemented under pressure until both of the following conditions have been met: 1) cement reaches a minimum compressive strength of 500 psi at the shoe, 2) until cement has been in place at least 8 hours. WOC time will be recorded in the driller's log. See individual casing strings for details regarding lead cement slurry requirements. (For surface casing the BOP can be nippled up after the cement has reached 500 psi compressive strength.)

No pea gravel permitted for remedial or fall back remedial without prior authorization from the BLM engineer.

Medium cave/karst

Possible water flows in Castile and Salado.

## Posible lost circulation in Rustler, Salado and Delaware.

- 1. The 10 3/4 inch surface casing shall be set at approximately 440 feet (a minimum of 25 feet into the Rustler Anhydrite and above the salt) and cemented to the surface. If salt is encountered, the operator shall set the casing 25' above the salt.
  - a. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with surface log readout will be used or a cement bond log shall be run to verify the top of the cement. Temperature survey will be run a minimum of six hours after pumping cement and ideally between 8-10 hours after completing the cement job.
  - b. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry.
  - c. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compressive strength, whichever is greater.
  - d. If cement falls back, remedial cementing will be done prior to drilling out that string.

Formation below the 10-3/4" shoe to be tested according to Onshore Order 2.III.B.1.i. Test to be done as a mud equivalency test using the mud weight necessary for the pore pressure of the formation below the shoe and the mud weight for the bottom of the hole. Report results to BLM office.

The 7-5/8 inch intermediate casing must be kept liquid filled while running into hole to meet minimum BLM requirements for collapse.

- 2. The minimum required fill of cement behind the 7-5/8 inch intermediate casing is:
  - a. First stage to DV tool:
  - Cement to circulate. If cement does not circulate, contact the appropriate BLM office before proceeding with second stage cement job. Operator should have plans as to how they will achieve circulation on the next stage.

Operator has proposed a contingency DV tool at 3075'. If operator circulates cement on the first stage, operator is approved to inflate the ACP and run the DV tool cancellation plug and cancel the second stage of the proposed cement plan. If cement does not circulate, operator will inflate ACP and proceed with the second stage.

- b. Second stage above DV tool:
- Cement to surface. If cement does not circulate see B.1.a, c-d above.

  Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry due to cave/karst.

Formation below the 7-5/8" shoe to be tested according to Onshore Order 2.III.B.1.i. Test to be done as a mud equivalency test using the mud weight necessary for the pore pressure of the formation below the shoe (not the mud weight required to prevent dissolving the salt formation) and the mud weight for the bottom of the hole. Report results to BLM office.

- 3. The minimum required fill of cement behind the 5-1/2 x 4-1/2 inch production casing is:
  - Cement should tie-back at least 500 feet into previous casing string. Operator shall provide method of verification.
- 4. If hardband drill pipe is rotated inside casing, returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.

CRW 103015