

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NMOCD
Artesia

FORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. NMNM29228
2. Name of Operator CIMAREX ENERGY COMPANY OF CO		6. If Indian, Allottee or Tribe Name
Contact: CRISTEN BURDELL E-Mail: cburdell@cimarex.com		7. If Unit or CA/Agreement, Name and/or No. NMNM128649
3a. Address 202 S CHEYENNE AVE SUITE 1000 TULSA, OK 74103.4346	3b. Phone No. (include area code) Ph: 918-560-7038	8. Well Name and No. BENSON 3 FED COM 8
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 3 T19S R30E NENE 375FNL 540FEL		9. API Well No. 30-015-37964-00-S1
		10. Field and Pool, or Exploratory LEO UNKNOWN
		11. County or Parish, and State EDDY COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

H2S gas analysis for facility as requested

NM OIL CONSERVATION
ARTESIA DISTRICT

JAN 04 2015

RECEIVED

Accepted for record
NMOCD

LRD 1/5/14

14. I hereby certify that the foregoing is true and correct. Electronic Submission #273878 verified by the BLM Well Information System For CIMAREX ENERGY COMPANY OF CO, sent to the Carlsbad Committed to AFMSS for processing by LINDA DENNISTON on 01/13/2015 (15LD0018SE)	
Name (Printed/Typed) CRISTEN BURDELL	Title REGULATORY ANALYST
Signature (Electronic Submission)	Date 10/27/2014

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By _____	Title _____
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	
Office _____	Office _____

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

Benson 3 Federal 8H

North Permian Basin Region

P.O. Box 740

Sundown, TX 79372-0740

(806) 229-8121

Lab Team Leader - Sheila Hernandez

(432) 495-7240

Water Analysis Report by Baker Petrolite

Company:	CIMAREX ENERGY	Sales RDT:	33512
Region:	PERMIAN BASIN	Account Manager:	WAYNE PETERSON (575) 910-9389
Area:	ARTESIA, NM	Sample #:	581314
Lease/Platform:	BENSON 3 FEDERAL COM	Analysis ID #:	120413
Entity (or well #):	8	Analysis Cost:	\$90.00
Formation:	UNKNOWN		
Sample Point:	HEATER TREATER		

Summary		Analysis of Sample 581314 @ 75 F					
Sampling Date:	04/21/12	Anions	mg/l	meq/l	Cations	mg/l	meq/l
Analysis Date:	05/12/12	Chloride:	149019.0	4203.28	Sodium:	74681.8	3248.48
Analyst:	STACEY SMITH	Bicarbonate:	60.0	0.98	Magnesium:	2095.0	172.34
TDS (mg/l or g/m3):	244105	Carbonate:	0.0	0.	Calcium:	14784.0	737.72
Density (g/cm3, tonne/m3):	1.162	Sulfate:	900.0	18.74	Strontium:	585.0	13.35
Anion/Cation Ratio:	1	Phosphate:			Barium:	0.7	0.01
		Borate:			Iron:	44.0	1.59
		Silicate:			Potassium:	1934.0	49.46
Carbon Dioxide:	600 PPM	Hydrogen Sulfide:		0	Aluminum:		
Oxygen:		pH at time of sampling:		6	Chromium:		
Comments:		pH at time of analysis:			Copper:		
RESISTIVITY: .04 OHM-M @ 75°F		pH used in Calculation:		6	Lead:		
					Manganese:	1.500	0.05
					Nickel:		

Conditions		Values Calculated at the Given Conditions - Amounts of Scale in lb/1000 bbl										
Temp	Gauge Press.	Calcite CaCO ₃		Gypsum CaSO ₄ ·2H ₂ O		Anhydrite CaSO ₄		Celestite SrSO ₄		Barite BaSO ₄		CO ₂ Press
°F	psi	Index	Amount	Index	Amount	Index	Amount	Index	Amount	Index	Amount	psi
80	0	-0.27	0.00	0.00	0.55	0.05	37.93	0.18	79.19	0.35	0.28	0.35
100	0	-0.20	0.00	-0.08	0.00	0.03	26.03	0.15	68.94	0.15	0.00	0.41
120	0	-0.12	0.00	-0.15	0.00	0.04	35.16	0.14	64.51	-0.02	0.00	0.48
140	0	-0.04	0.00	-0.21	0.00	0.08	61.19	0.14	64.23	-0.17	0.00	0.54

Note 1: When assessing the severity of the scale problem, both the saturation index (SI) and amount of scale must be considered.

Note 2: Precipitation of each scale is considered separately. Total scale will be less than the sum of the amounts of the five scales.

Note 3: The reported CO₂ pressure is actually the calculated CO₂ fugacity. It is usually nearly the same as the CO₂ partial pressure.