Form 3160-5 (August 2007)

UNITED STATES


FORM APPROVED OMB NO. 1004-0135

Up	Expires: July 31, 2010						
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				Lease Serial No. NMLC030570A If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit of CA/Agreement, Name and/or No.			
I. Type of Well				8, Well Name and No. GJSAU 13			
Ø Oil Well ☐ Gas Well ☐ Oth 2. Name of Operator		IE CADVIC		9. API Well No.			
BURNETT OIL CO. INC. E-Mail: Igarvis@burnettoll.com				30-015-04145			
3a. Address: BURNETT PLAZA - SUITE 1500 801 CHERRY STREETPHJNITFORF8/18IRTH, TX 76102 FORT WORTH, TX 76102				10. Field and Pool, or Exploratory GRAYBURG JACKSON			
4. Location of Well (Footage, Sec., T. R., M., or Survey Description)				11. County or Parish, and State			
Sec 13 T17S R30E Mer NMP		EDDY COUNTY, NM					
·			}				
12. CHECK APPI	ROPRIATE BOX(ES) TO IND	ICATE NATURE OF	NOTICE, RE	PORT, OR OTHE	R DATA		
TYPE OF SUBMISSION	TYPE OF ACTION						
□ Notice of Intent	☐ Acidize	Deepen	Producti	on (Start/Resume)	☐ Water Shu	ıt-Off	
_	☐ Alter Casing	☐ Fracture Treat	☐ Reclama	on		rity	
Subsequent Report	Casing Repair	New Construction	□ Recomp	lete	Other	.,	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	☐ Tempor	arily Abandon	Workover O	perations	
	☐ Convert to Injection	☐ Plug Back	☐ Water D	isposal			
Attach the Bond under which the wor following completion of the involved	ally or recomplete horizontally, give su it will be performed or provide the Boa operations. If the operation results in andonment Notices shall be filed only	bsurface locations and meast nd No. on file with BLM/BI/ a multiple completion or rec	ured and true ver A. Required sub completion in a n	rtical depths of all pertir sequent reports shall be ew interval, a Form 316	nent markers and z : fîled within 30 dø :0-4 shall be fîled (rones. 1ys once	
11/26/14 - MIRU, ND WELLHI	EAD, REL AD-1 PKR, NUBOP						
12/1/14 - POOH W/TBG AND	PKR BULLPLUG TBG TEST IN	HOLE TO 1000# HAD	10 BAD JTS	S.POOH TBG.	-		
12/2/14 RIH 4 1/2 AD-1 PKR 2789 NU WELLHEAD TESTE BLM witnessed.	AND TBG PICKUP 9 JTS TO I D TO 560 FOR 30 MIN GAINE	REPLACE BAD JTS. C D 30# TO 590 WILL R	IRCULATE P ETEST THIS	PKR FLUID SET PK AM PAUL SWAR	IR @ TZ with		
12/3/14 - TEST AND CHART / ON LOCATION	ANNULUS TO 570# FOR 30 MI	IN LOST 10# TO 560 T	EST IS GOO	D. PAUL SWARTZ	BLM		
NOTE: MIT TEST SENT PRE	VIOUSLY IN SEPARATE SN.			C.			
Pkr may be s	ct well above in	jzone like	c 4901		ECT TO LII		
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #331881	verified by the BI M We	II Information	APPK	UVAL BY	SIATE	
	For BURNETT OIL	. CO. InC., sent to the C	arlabad	- Jacon			
Name(Printed/Typed) LESLIE G	Title REGUL	Title REGULATORY COORDINATOR					
		- VU	FPTED FOI	RECOR	n		
Signature (Electronic S	ubmission)	Date 02/22/2	016 701	ALI ILD I VI	INLOUN	U	
`	THIS SPACE FOR FE	DERAL OR STATE	OFFICE US	IR			
A	Tale		FEB 25	2016	=		
Approved_ByConditions of approval, if any, are attached	Title		Thomas	Enh			
conditions of approval, it any, are anactice certify that the applicant holds legal or equivalent would entitle the applicant to conduction.		Office		UREAU OF LAND MANAGEMENT			
Title 18 U.S.C. Section 1001 and Title 43 I States any false, fictitious or fraudulent s	J.S.C. Section 1212, make it a crime for	or any person knowingly and	willfully to mal	ce the ally department of	agency of the Unit	ted	
meres ally raise, treatmers of mandalent s	remember rate of refresching from 172 to 1111 A. I	namet within its juristiction.					

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

2/26/16

ACCORDED TO THE OPERATOR SUBMITTED ** NINOCD



10 pt 1



RE: Well GB JACKSON SA 13

3 messages

Leslie Garvis <lgarvis@burnettoil.com>
To: "Paul Swartz@blm.gov" <Paul Swartz@blm.gov>

Thu, Feb 25, 2016 at 3:38 PM

Thanks Paul.

LESLIE M. GARVIS
REGULATORY COORDINATOR
BURNETT OIL CO., INC.
BURNETT PLAZA-SUITE 1500
801 CHERRY STREET - UNIT #9
FORT WORTH, TX 76102-6881
DIRECT LINE: 817.583.8730
MOBILE: 713.819.4371

MOBILE: 713.819.4371 FAX: (817) 332-2438

EMAIL: LGARVIS@BURNETTOIL.COM

----Original Message----

From: Paul_Swartz@blm.gov [mailto:Paul_Swartz@blm.gov]

Sent: Thursday, February 25, 2016 4:35 PM

To: Leslie Garvis

Subject: Well GB JACKSON SA 13

The sundry for Workover Operations you submitted has been accepted by the BLM. Your original Electronic Commerce (EC) transmission was assigned ID 331881. Please be sure to open and save all attachments to this message, since they contain important information.

Thanks Leslie.

This message is intended only for the person(s) to which it is addressed and may contain privileged, confidential and/or insider information. If you have received this communication in error, please notify us immediately by replying to the message and deleting it from your computer. Any disclosure, copying, distribution, or the taking of any action concerning the contents of this message and any attachment(s) by anyone other than the named recipient(s) is strictly prohibited.

Swartz, Paul <pswartz@bim.gov>
To: Leslie Garvis <|garvis@bumettoil.com>

Thu, Feb 25, 2016 at 5:01 PM

Leslie,

From the subsequent report it looks like the packer may have been set several hundred feet high per usual injection well configuration. Suspect NMOCD will also be concerned. Have not found NMOCD documentation setting the well up for injection status. Left a message for NMOCD's Randy Dade in Artesia. There could be an explanation, but it is not apparent at this time. If not, Burnett needs to offer to bring the well into compliance.

We seem to have plowed up a snake.

pswartz 575-200-7902 [Quoted text hidden]