OCD ARTESIS

Form 3160-5 (August 2007) **UNITED STATES**

NM OIL CONSERVATION

DEPARTMENT OF THE INTERIOR ARTESIA DISTRICT

BUREAU OF LAND MANAGEMENT FEB 2 9 2016

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS

5. Lease Serial No. NM0533177-A 6. If Indian, Allottee or Tribe Name

| SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well | Do not use this form for particles abandoned well. Use Form | posals to drill or to 1160-3 (APD) for suc | recenter TED | | | | |
|--|--|---|---|-----------------------|--|--|------------|
| Type of Well Gas Well Other S. Well Name and No. TODO 24 G FEDERAL #7 Power of Production Company Power of Power of Production Company Power of Power o | SUBMIT IN TRIPLICATE – Other instructions on page 2. | | | | 7. If Unit of CA/Agreement, Name and/or No. | | |
| 2. Name of Open Completion Completion Completion Completed Open Converted Integrity Production (Start/Resume) Open Completed Open Converted Integrity State Control Coloring Plans Open Converted Integrity State Control Coloring Plans Open Converted Integrity State Coloring Converted Integrity of Converted Integri | | | | | | | |
| 33. Address 33. West Stemation Anomue, Ostathoma City, Or. 73102-5015 35. Phone No. (Include area code) 10. Field and Peol or Exploratory Area 11. Country or Parish, State 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA 17. | ✓ Oil Well ☐ Gas Well ☐ Other | | | | | | |
| 33. Address 33. West Stemation Anomue, Ostathoma City, Or. 73102-5015 35. Phone No. (Include area code) 10. Field and Peol or Exploratory Area 11. Country or Parish, State 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA 17. | 2. Name of Operator DEVON ENERGY PRODUCTION COMPANY, LP | | | | 9. API Well No. 1.30-015-27692 | | |
| 4. Location of Well (Footage, Sec., T.R.M., or Survey Description) 11. Country or Parish, State EDDY, NM | 3a. Address 3b. Phone No | | | I | | | |
| 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACIDIO Notice of Intent | 333 West Sheridan Avenue, Oklahoma City, OK 73102-5015 | | | INGLE | | | |
| TYPE OF SUBMISSION Notice of Intent | 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 1650 FNL & 2310 FEL; SEC 24-T23S-R31E | | | | 1 | | |
| Notice of Intent | 12. CHECK THE APPR | PRIATE BOX(ES) TO INDI | CATE NATURE OF | NOTICE, REP | ORT OR OTHER | DATA | |
| Alter Casing Fracture Treat Reclamation Well Integrity | TYPE OF SUBMISSION | | ТҮРЕ (| OF ACTION | | · · · · | |
| Alter Casing | Notice of Intent | Acidize Deepe | | Production (S | action (Start/Resume) Water Shut-Off | | |
| Plug and Abandon Temporarily Abandon Temporarily Abandon Plug Back Water Disposal | | sing Fractu | re Treat | Reclamation | ! | Well Integrity | |
| Change Plans | Subsequent Report Casing | tepair New C | Construction | Recomplete | ! | Other | |
| 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration there the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed ont testing has been completed. Final Abandomment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 1. 1/22/16-MIRU P&A Unit. 2. POOH w/rod string, pump, and 2-7/8" production assembly. Tagged PBD @ 8,511'. 3. Spot 45 sx CI H @ 8,500'. Tagged deeper @ 8,503'. Re-spot 35 sx CI H @ 8,503'. Tagged @ 7,706'. BLM approved. 4. Set CIBP @ 6,765'. Spot 25 sx (250') CI C @ 6,765' - 6,515'. (Delaware perfs @ 6,804' - 8,342') 5. Spot 30 sx CI C @ 4,594'. Tagged TOC @ 5,086' (DV @ 5,283') 6. Spot 240 sx CI C @ 4,594'. Tagged TOC @ 5,086' (DV @ 5,283') 6. Spot 240 sx CI C @ 4,594'. Tagged TOC @ 3,086' (DV @ 5,283') 6. Spot 240 sx CI C @ 4,594'. Tagged TOC @ 9,086' (DV @ 5,283') 6. Spot 30 st C @ 4,596' shoe @ 4,359'; B.Salt @ 4,273'; T.Salt @ 1,222'; 13-3/8" shoe @ 858'. Well in R-111P). 7. Cut casings off. Top out 8-5/8' casing. 8. Set BGL dry hole marker. Wellbore plugged & abandoned-2/1/16. 9# mud circulated between plugs. Accepted as to plugging of the well bore, Surface restoration is completed. Title Production Technologist Title Production Technologist Date 2-2-16 | | | nd Abandon | Temporarily I | Temporarily Abandon | | |
| the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion for recompletion in a new interval, a Form 3160-4 must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 1. 1/22/16-MIRU P&A Unit. 2. POOH w/rod string, pump, and 2-7/8" production assembly. Tagged PBD @ 8,511'. 3. Spot 45 sx Cl H @ 8,500'. Tagged deeper @ 8,503'. Re-spot 35 sx Cl H @ 8,503'. Tagged @ 7,706'. BLM approved. 4. Set ClBP @ 6,765'. Spot 25 sx (250') Cl C @ 6,765' - 6,515'. (Delaware perfs @ 6,804' - 8,342') 5. Spot 30 sx Cl C @ 6,384'. Tagged TOC @ 5,086'. (DV @ 5,283') 6. Spot 240 sx Cl C @ 4,594'. Tagged TOC @ 2,144'. Spot 135 sx Cl C @ 2,144'. Tagged TOC @ 929'. Spot 95 sx Cl C from 929' to surface. (Top of Delaware @ 4,556'; 8-5/8'' shoe @ 4,359'; B.Salt @ 4,273'; T.Salt @ 1,222'; 13-3/8" shoe @ 858'. Well in R-111P). 7. Cut casings off. Top out 8-5/8' casing. 8. Set BGL dry hole marker. Wellbore plugged & abandoned-2/1/16. 9# mud circulated between plugs. Accepted as to plugging of the well bore, Surface restoration is completed. **Production Technologist** Title Production Technologist** Due 2 - 2 - 1/6 ***Date of the well bore. Surface restoration is completed.** Date 2 - 2 - 1/6 | Final Abandonment Notice Conve | to Injection Plug B | Back | Water Dispos | r Disposal | | |
| Accepted as to plugging of the well bore. RECLAMATION DUE 8-C-IC Accepted as to plugging of the well bore. Liability under bond is retained until Surface restoration is completed. Title Production Technologist Date 2-2-16 | OH w/rod string, pump, and 2-7/8" product to 45 sx Cl H @ 8,500'. Tagged deeper @ 8 ClBP @ 6,765'. Spot 25 sx (250') Cl C @ to 30 sx Cl C @ 5,384'. Tagged TOC @ 5,6 to 240 sx Cl C @ 4,594'. Tagged TOC @ 2 are @ 4,556'; 8-5/8" shoe @ 4,359'; B.Salicasings off. Top out 8-5/8" casing. BGL dry hole marker. Wellbore plugged 8 | 503'. Re-spot 35 sx Cl H @ ,765' - 6,515'. (Delaware pe 6'. (DV @ 5,283') 44'. Spot 135 sx Cl C @ 2, ∄ 4,273'; T.Salt @ 1,222'; 1 | 8,503'. Tagged @ erfs @ 6,804' - 8,3 144'. Tagged TOC | 42') @ 929'. Spot! | 95 sx Cl C from 9 | 929' to surface. (Top of | - 1 |
| 14. I hereby certify that the foregoing is frueland correct. Name (Printed/Typed) Ronnie Slack Title Production Technologist Date 2-2-16 | a circulated between plugs. | | | | | | ł |
| Name (Printed/Typed) Ronnie Slack Title Production Technologist Date 2-2-16 | | RECLAN DUE_8- | MATION -(-/C_ | Acc Lial Suri | cepted as to plu bility under bor face restoration | issing of the well bore, not is retained until is completed. | |
| Ronnie Stack Title Production Technologist Date 2-2-16 | | | | | * . | The same of the same of the | |
| | | | | | | <u>,</u> | |
| / | Signature Ronnie Stack Date 2-2-16 | | | | | | |
| Accepted for Record THIS SPACE FOR FEDERAL OR STATE OFFICE USE | ested for Record THI | SPACE FOR FEDER | RAL OR STATI | E OFFICE (| JSE | | |
| Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title SALT Date Z-17-/S Office Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office Title SALT Date Z-17-/S Office | ins of approval, if any, are attached. Approval of applicant holds legal or equitable title to those rigile applicant to conduct operations thereon. U.S.C. Section 1001 and Title 43 U.S.C. Section | in the subject lease which wou | office Son knowingly and wi | 10 | | | alse |

