

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.
NM-22614
6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well
 Oil Well Gas Well Other PA

7. If Unit or CA/Agreement, Name and/or No.

2. Name of Operator
Lime Rock Resources A, L.P.

8. Well Name and No.
Mike Harvey TR Federal #4

3a. Address
1111 Bagby Street, Suite 4600, Houston, Tx 77002

3b. Phone No. (include area code)
575-748-1471

9. API Well No.
30-005-61878

4. Location of Well (Footage, Sec., T., R., M., OR Survey Description)
1780' FNL & 2480' FWL of Section 3-T5S-R24E (SENW)

10. Field and Pool or Exploratory Area
Pecos Slope Abo

11. County or Parish, State
Chaves County, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input checked="" type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomplate in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Lime Rock Resources A, L.P. respectfully requests final abandonment approval and the release of liability under bond. All requirements for reclamation have been met.

NM OIL CONSERVATION
ARTESIA DISTRICT

MAR 18 2008

Accepted for record
NMOC

RECEIVED

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)
Michelle Taylor- Contract for Lime Rock Resources Title Regulatory Compliance Manager

Signature *[Signature]* Date February 4, 2008

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by *[Signature]* Ruben J. Sanchez Title Lands And Minerals Date MAR 08 2016

Office ROSWELL FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction